

## HCT Co., Ltd.


74, Seoicheon-ro 578beon-gil, Majang-myeon, Icheon-si, Gyeonggi-do, 17383 KOREA Tel. +82 31 634 6300 Fax. +82 31 645 6401

## **REVISION HISTORY**

The revision history for this document is shown in table.

Revision No.	Date of Issue	Description
0	October 28, 2022	Initial Release

	HCT-RF-2209-FC007-P	HCT-RF-2210-FC010-P	HCT-RF-2210-FC011-P	HCT-RF-2210-FC012-P	HCT-RF-2210-FC013-P
File	HCT-RF-2210-FC014-P	HCT-RF-2210-FC015-P	HCT-RF-2210-FC016-P	HCT-RF-2210-FC017-P	HCT-RF-2210-FC018-P
No.	HCT-RF-2210-FC019-P	HCT-RF-2210-FC020-P	HCT-RF-2210-FC021-P	HCT-RF-2210-FC022-P	HCT-RF-2210-FC023-P
	HCT-RF-2210-FC024-P				






## 1. Radiated Test Setup Photo






































































































































## 2. Conducted Test Setup Photo

