



Appendix D. #Antenna Location & Distance



Front View



KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR21-SPF0075-B
Page (66) of (72)



Appendix E. EUT Photo

E.1)Front



E.2)Rear



KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR21-SPF0075-B
Page (67) of (72)



E.3)Left



E.4)Right



E.5)Top



E.6)Bottom



Appendix F. Test Setup Photo

F.1)Body_Rear (0 mm)




F.2)Body_Rear (10 mm)



F.3)Body_Right (0 mm)



F.4)Body_Right corner 30° (0 mm)




KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR21-SPF0075-B
Page (71) of (72)



F.5)Body_Right corner 45° (0 mm)



F.6)Body_Bottom (0 mm)



KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR21-SPF0075-B
Page (72) of (72)



F.7)Body_Bottom (10 mm)



End of test report