



Appendix E. #Antenna Location & Distance

* Placement of each antenna




* Distance between Main antenna and edge




* Distance between WLAN antenna antenna and edge

Rear View



* Distance between BT/WLAN antenna antenna and edge

Rear View



KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR20-SPF0035-B
Page (325) of (338)



Appendix F. EUT Photo

Front



Rear



KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR20-SPF0035-B
Page (326) of (338)



Left



Right



KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR20-SPF0035-B
Page (327) of (338)

KCTL

Top



Bottom



Appendix G. Test Setup Photo

Appendix G.1 Test Setup Photo (Head)

Right Cheek



Right Tilt



KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR20-SPF0035-B
Page (329) of (338)



Left Cheek



Left Tilt



KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR20-SPF0035-B
Page (330) of (338)



Right Cheek With Protective Cover



Left Cheek With Protective Cover



KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR20-SPF0035-B
Page (331) of (338)




Appendix G.2 Test Setup Photo (Body)


Rear (0mm)



Rear (12mm)



Rear (19 mm)




Rear With Protective Cover (0 mm)



Rear With Protective Cover (12 mm)



Rear With Protective Cover (19 mm)



KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR20-SPF0035-B
Page (334) of (338)



Left (0 mm)



Left (5 mm)



KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR20-SPF0035-B
Page (335) of (338)



Left With Protective Cover (5 mm)



Right (0 mm)



KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR20-SPF0035-B
Page (336) of (338)



Right (6 mm)



Top (0 mm)



Top (7 mm)



Top (14 mm)



KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR20-SPF0035-B
Page (338) of (338)



Top With Protective Cover (7 mm)



Top With Protective Cover (14 mm)



End of test report