



HCT Co., Ltd.

74, Seoicheon-ro 578beon-gil, Majang-myeon, Icheon-si, Gyeonggi-do, 17383 KOREA
Tel. +82 31 634 6300 Fax. +82 31 645 6401

<h1 style="margin: 0;">Appendix A: Test Setup Photo</h1>	<p>FCC ID A3LSMX610</p> <p>File No.</p> <table border="0"> <tr> <td>HCT-RF-2307-FC024-P</td> <td>HCT-RF-2307-FC028-P</td> </tr> <tr> <td>HCT-RF-2307-FC025-P</td> <td>HCT-RF-2307-FC029-P</td> </tr> <tr> <td>HCT-RF-2307-FC026-P</td> <td>HCT-RF-2307-FC030-P</td> </tr> <tr> <td>HCT-RF-2307-FC027-P</td> <td>HCT-RF-2307-FC031-P</td> </tr> </table>	HCT-RF-2307-FC024-P	HCT-RF-2307-FC028-P	HCT-RF-2307-FC025-P	HCT-RF-2307-FC029-P	HCT-RF-2307-FC026-P	HCT-RF-2307-FC030-P	HCT-RF-2307-FC027-P	HCT-RF-2307-FC031-P
HCT-RF-2307-FC024-P	HCT-RF-2307-FC028-P								
HCT-RF-2307-FC025-P	HCT-RF-2307-FC029-P								
HCT-RF-2307-FC026-P	HCT-RF-2307-FC030-P								
HCT-RF-2307-FC027-P	HCT-RF-2307-FC031-P								

REVISION HISTORY


The revision history for this document is shown in table.

Revision No.	Date of Issue	Description
0	July 24, 2023	Initial Release


File No.	HCT-RF-2307-FC024-P	HCT-RF-2307-FC025-P	HCT-RF-2307-FC026-P	HCT-RF-2307-FC027-P	HCT-RF-2307-FC028-P
	HCT-RF-2307-FC029-P	HCT-RF-2307-FC030-P	HCT-RF-2307-FC031-P		


1. Radiated Test Setup Photo


Radiated spurious emissions & Restricted Band Edge (Above 1 GHz)





File No.	HCT-RF-2307-FC024-P	HCT-RF-2307-FC025-P	HCT-RF-2307-FC026-P	HCT-RF-2307-FC027-P	HCT-RF-2307-FC028-P
	HCT-RF-2307-FC029-P	HCT-RF-2307-FC030-P	HCT-RF-2307-FC031-P		












Radiated spurious emissions (Below 1GHz)



File No.	HCT-RF-2307-FC024-P	HCT-RF-2307-FC025-P	HCT-RF-2307-FC026-P	HCT-RF-2307-FC027-P	HCT-RF-2307-FC028-P
	HCT-RF-2307-FC029-P	HCT-RF-2307-FC030-P	HCT-RF-2307-FC031-P		













WPT Radiated Test Setup Photo for 9 kHz ~30 MHz:



File No.	HCT-RF-2307-FC024-P	HCT-RF-2307-FC025-P	HCT-RF-2307-FC026-P	HCT-RF-2307-FC027-P	HCT-RF-2307-FC028-P
	HCT-RF-2307-FC029-P	HCT-RF-2307-FC030-P	HCT-RF-2307-FC031-P		










File No.	HCT-RF-2307-FC024-P	HCT-RF-2307-FC025-P	HCT-RF-2307-FC026-P	HCT-RF-2307-FC027-P	HCT-RF-2307-FC028-P
	HCT-RF-2307-FC029-P	HCT-RF-2307-FC030-P	HCT-RF-2307-FC031-P		











2. Conducted Test Setup Photo



File No.	HCT-RF-2307-FC024-P	HCT-RF-2307-FC025-P	HCT-RF-2307-FC026-P	HCT-RF-2307-FC027-P	HCT-RF-2307-FC028-P
	HCT-RF-2307-FC029-P	HCT-RF-2307-FC030-P	HCT-RF-2307-FC031-P		

3. DFS Test Setup Photo



File No.	HCT-RF-2307-FC024-P	HCT-RF-2307-FC025-P	HCT-RF-2307-FC026-P	HCT-RF-2307-FC027-P	HCT-RF-2307-FC028-P
	HCT-RF-2307-FC029-P	HCT-RF-2307-FC030-P	HCT-RF-2307-FC031-P		

4. AC Power Line Conducted Test Setup Photo



File No.	HCT-RF-2307-FC024-P	HCT-RF-2307-FC025-P	HCT-RF-2307-FC026-P	HCT-RF-2307-FC027-P	HCT-RF-2307-FC028-P
	HCT-RF-2307-FC029-P	HCT-RF-2307-FC030-P	HCT-RF-2307-FC031-P		