




**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03423  
 Page (150) / (248) Pages



**ANT1\_802.11ax\_HE20\_26T\_Low\_UNII 5**






**ANT1\_802.11ax\_HE20\_26T\_Low\_UNII 6**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03423  
 Page (151) / (248) Pages



ANT1\_802.11ax\_HE20\_26T\_Low\_UNII 7





ANT1\_802.11ax\_HE20\_26T\_Low\_UNII 8






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03423  
 Page (152) / (248) Pages



**ANT2\_802.11ax\_HE20\_26T\_Low\_UNII 5**





**ANT2\_802.11ax\_HE20\_26T\_Low\_UNII 6**




**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03423  
 Page (153) / (248) Pages



**ANT2\_802.11ax\_HE20\_26T\_Low\_UNII 7**





**ANT2\_802.11ax\_HE20\_26T\_Low\_UNII 8**





**CTK Co., Ltd.**  
(Ho-dong), 113, Yejik-ro, Cheoin-gu,  
Yongin-si, Gyeonggi-do, Korea  
Tel: +82-31-339-9970  
Fax: +82-31-624-9501

Report No.:  
CTK-2021-03423  
Page (154) / (248) Pages



**ANT1\_802.11ax\_HE20\_26T\_Mid\_UNII 5**






**ANT1\_802.11ax\_HE20\_26T\_Mid\_UNII 6**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03423  
 Page (155) / (248) Pages



**ANT1\_802.11ax\_HE20\_26T\_Mid\_UNII 7**






**ANT1\_802.11ax\_HE20\_26T\_Mid\_UNII 8**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03423  
 Page (156) / (248) Pages



**ANT2\_802.11ax\_HE20\_26T\_Mid\_UNI1 5**




**ANT2\_802.11ax\_HE20\_26T\_Mid\_UNI1 6**







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03423  
 Page (157) / (248) Pages



**ANT2\_802.11ax\_HE20\_26T\_Mid\_UNII 7**






**ANT2\_802.11ax\_HE20\_26T\_Mid\_UNII 8**








**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03423  
 Page (158) / (248) Pages



**ANT1\_802.11ax\_HE20\_26T\_High\_UNII 5**






**ANT1\_802.11ax\_HE20\_26T\_High\_UNII 6**







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03423  
 Page (159) / (248) Pages



**ANT1\_802.11ax\_HE20\_26T\_High\_UNII 7**






**ANT1\_802.11ax\_HE20\_26T\_High\_UNII 8**






**CTK Co., Ltd.**  
(Ho-dong), 113, Yejik-ro, Cheoin-gu,  
Yongin-si, Gyeonggi-do, Korea  
Tel: +82-31-339-9970  
Fax: +82-31-624-9501

Report No.:  
CTK-2021-03423  
Page (160) / (248) Pages



### ANT2\_802.11ax\_HE20\_26T\_High\_UNII 5






### ANT2\_802.11ax\_HE20\_26T\_High\_UNII 6






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2021-03423  
 Page (161) / (248) Pages




**ANT2\_802.11ax\_HE20\_26T\_High\_UNII 7**



**ANT2\_802.11ax\_HE20\_26T\_High\_UNII 8**



ANT1\_802.11ax\_HE40\_26T\_Low\_UNII 5





ANT1\_802.11ax\_HE40\_26T\_Low\_UNII 6




**CTK Co., Ltd.**  
(Ho-dong), 113, Yejik-ro, Cheoin-gu,  
Yongin-si, Gyeonggi-do, Korea  
Tel: +82-31-339-9970  
Fax: +82-31-624-9501

Report No.:  
CTK-2021-03423  
Page (163) / (248) Pages



ANT1\_802.11ax\_HE40\_26T\_Low\_UNII 7




ANT1\_802.11ax\_HE40\_26T\_Low\_UNII 8



**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03423  
 Page (164) / (248) Pages



**ANT2\_802.11ax\_HE40\_26T\_Low\_UNI I 5**




**ANT2\_802.11ax\_HE40\_26T\_Low\_UNI I 6**




**CTK Co., Ltd.**  
(Ho-dong), 113, Yejik-ro, Cheoin-gu,  
Yongin-si, Gyeonggi-do, Korea  
Tel: +82-31-339-9970  
Fax: +82-31-624-9501

Report No.:  
CTK-2021-03423  
Page (165) / (248) Pages






ANT2\_802.11ax\_HE40\_26T\_Low\_UNII 7





ANT2\_802.11ax\_HE40\_26T\_Low\_UNII 8











**ANT1\_802.11ax\_HE40\_26T\_Mid\_UNII 5**



**ANT1\_802.11ax\_HE40\_26T\_Mid\_UNII 6**



**ANT1\_802.11ax\_HE40\_26T\_Mid\_UNII 7**






**ANT1\_802.11ax\_HE40\_26T\_Mid\_UNII 8**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03423  
 Page (168) / (248) Pages



**ANT2\_802.11ax\_HE40\_26T\_Mid\_UNII 5**



**ANT2\_802.11ax\_HE40\_26T\_Mid\_UNII 6**