









CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (62) / (376) Pages



ANT1_802.11ax_HE20_26T_High_UNII 2C






ANT1_802.11ax_HE20_26T_High_UNII 3






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (63) / (376) Pages



ANT2_802.11ax_HE20_26T_High_UNI 1






ANT2_802.11ax_HE20_26T_High_UNI 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (64) / (376) Pages



ANT2_802.11ax_HE20_26T_High_UNII 2C





ANT2_802.11ax_HE20_26T_High_UNII 3





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2021-03418
 Page (65) / (376) Pages



ANT1_802.11n_HT40_UNI I 1



ANT1_802.11n_HT40_UNI I 2A





ANT1_802.11n_HT40_UNI I 2C



CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (66) / (376) Pages





ANT1_802.11n_HT40_UNII 3





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2021-03418
 Page (67) / (376) Pages



ANT2_802.11n_HT40_UNI I 1



ANT2_802.11n_HT40_UNI I 2A





ANT2_802.11n_HT40_UNI I 2C



CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (68) / (376) Pages





ANT2_802.11n_HT40_UNI1 3





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501



Report No.:
 CTK-2021-03418
 Page (69) / (376) Pages




ANT1_802.11ac_VHT40_UNI1



ANT1_802.11ac_VHT40_UNI1 2A





ANT1_802.11ac_VHT40_UNI1 2C





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (70) / (376) Pages





ANT1_802.11ac_VHT40_UNII 3





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2021-03418
 Page (71) / (376) Pages



ANT2_802.11ac_VHT40_UNII 1



ANT2_802.11ac_VHT40_UNII 2A





ANT2_802.11ac_VHT40_UNII 2C



CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (72) / (376) Pages





ANT2_802.11ac_VHT40_UNII 3





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501



Report No.:
 CTK-2021-03418
 Page (73) / (376) Pages




ANT1_802.11ax_HE40_SU_UNI1 1



ANT1_802.11ax_HE40_SU_UNI1 2A





ANT1_802.11ax_HE40_SU_UNI1 2C





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (74) / (376) Pages





ANT1_802.11ax_HE40_SU_UNI I 3





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501



Report No.:
 CTK-2021-03418
 Page (75) / (376) Pages




ANT2_802.11ax_HE40_SU_UNI1 1



ANT2_802.11ax_HE40_SU_UNI1 2A





ANT2_802.11ax_HE40_SU_UNI1 2C





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (76) / (376) Pages





ANT2_802.11ax_HE40_SU_UNI I 3




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2021-03418
 Page (77) / (376) Pages



ANT1_802.11ax_HE40_26T_Low_UNII 1



ANT1_802.11ax_HE40_26T_Low_UNII 2A





ANT1_802.11ax_HE40_26T_Low_UNII 2C



CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (78) / (376) Pages





ANT1_802.11ax_HE40_26T_Low_UNI I 3





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2021-03418
 Page (79) / (376) Pages



ANT2_802.11ax_HE40_26T_Low_UNII 1



ANT2_802.11ax_HE40_26T_Low_UNII 2A





ANT2_802.11ax_HE40_26T_Low_UNII 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2021-03418
Page (80) / (376) Pages





ANT2_802.11ax_HE40_26T_Low_UNI I 3





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2021-03418
 Page (81) / (376) Pages



ANT1_802.11ax_HE40_26T_Mid_UNII 1



ANT1_802.11ax_HE40_26T_Mid_UNII 2A





ANT1_802.11ax_HE40_26T_Mid_UNII 2C



CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (82) / (376) Pages





ANT1_802.11ax_HE40_26T_Mid_UNII 3





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2021-03418
 Page (83) / (376) Pages



ANT2_802.11ax_HE40_26T_Mid_UNII 1



ANT2_802.11ax_HE40_26T_Mid_UNII 2A





ANT2_802.11ax_HE40_26T_Mid_UNII 2C



CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (84) / (376) Pages





ANT2_802.11ax_HE40_26T_Mid_UNII 3





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2021-03418
 Page (85) / (376) Pages



ANT1_802.11ax_HE40_26T_High_UNI 1



ANT1_802.11ax_HE40_26T_High_UNI 1A





ANT1_802.11ax_HE40_26T_High_UNI 1C



CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (86) / (376) Pages





ANT1_802.11ax_HE40_26T_High_UNI 3





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2021-03418
 Page (87) / (376) Pages



ANT2_802.11ax_HE40_26T_High_UNI 1



ANT2_802.11ax_HE40_26T_High_UNI 1A





ANT2_802.11ax_HE40_26T_High_UNI 1C



CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (88) / (376) Pages



ANT2_802.11ax_HE40_26T_High_UNI 3