




ANT1_802.11n_HT20_UNII 1




ANT1_802.11n_HT20_UNII 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (42) / (376) Pages



ANT1_802.11n_HT20_UNII 2C






ANT1_802.11n_HT20_UNII 3






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (43) / (376) Pages



ANT2_802.11n_HT20_UNII 1






ANT2_802.11n_HT20_UNII 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (44) / (376) Pages



ANT2_802.11n_HT20_UNII 2C






ANT2_802.11n_HT20_UNII 3






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (45) / (376) Pages



ANT1_802.11ac_VHT20_UNII 1






ANT1_802.11ac_VHT20_UNII 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (46) / (376) Pages



ANT1_802.11ac_VHT20_UNII 2C






ANT1_802.11ac_VHT20_UNII 3






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (47) / (376) Pages



ANT2_802.11ac_VHT20_UNII 1






ANT2_802.11ac_VHT20_UNII 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (48) / (376) Pages



ANT2_802.11ac_VHT20_UNI1 2C






ANT2_802.11ac_VHT20_UNI1 3






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (49) / (376) Pages



ANT1_802.11ax_HE20_SU_UNI 1






ANT1_802.11ax_HE20_SU_UNI 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (50) / (376) Pages



ANT1_802.11ax_HE20_SU_UNI 2C






ANT1_802.11ax_HE20_SU_UNI 3






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (51) / (376) Pages



ANT2_802.11ax_HE20_SU_UNI 1






ANT2_802.11ax_HE20_SU_UNI 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (52) / (376) Pages



ANT2_802.11ax_HE20_SU_UNI 2C






ANT2_802.11ax_HE20_SU_UNI 3






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (53) / (376) Pages



ANT1_802.11ax_HE20_26T_Low_UNII 1






ANT1_802.11ax_HE20_26T_Low_UNII 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (54) / (376) Pages



ANT1_802.11ax_HE20_26T_Low_UNII 2C






ANT1_802.11ax_HE20_26T_Low_UNII 3






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (55) / (376) Pages



ANT2_802.11ax_HE20_26T_Low_UNII 1






ANT2_802.11ax_HE20_26T_Low_UNII 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2021-03418
 Page (56) / (376) Pages






ANT2_802.11ax_HE20_26T_Low_UNII 2C



ANT2_802.11ax_HE20_26T_Low_UNII 3



ANT1_802.11ax_HE20_26T_Mid_UNI1 1






ANT1_802.11ax_HE20_26T_Mid_UNI1 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (58) / (376) Pages



ANT1_802.11ax_HE20_26T_Mid_UNII 2C






ANT1_802.11ax_HE20_26T_Mid_UNII 3






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (59) / (376) Pages



ANT2_802.11ax_HE20_26T_Mid_UNII 1






ANT2_802.11ax_HE20_26T_Mid_UNII 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (60) / (376) Pages



ANT2_802.11ax_HE20_26T_Mid_UNI1 2C






ANT2_802.11ax_HE20_26T_Mid_UNI1 3






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (61) / (376) Pages



ANT1_802.11ax_HE20_26T_High_UNI 1



ANT1_802.11ax_HE20_26T_High_UNI 2A