




ANT1_802.11a_UNII 2C






ANT1_802.11a_UNII 3






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2021-03418
Page (143) / (376) Pages



ANT2_802.11a_UNII 1






ANT2_802.11a_UNII 2A






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2021-03418
Page (144) / (376) Pages



ANT2_802.11a_UNII 2C






ANT2_802.11a_UNII 3






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2021-03418
 Page (145) / (376) Pages






ANT1_802.11n_HT20_UNII 1



ANT1_802.11n_HT20_UNII 2A



ANT1_802.11n_HT20_UNII 2C






ANT1_802.11n_HT20_UNII 3






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (147) / (376) Pages



ANT2_802.11n_HT20_UNII 1






ANT2_802.11n_HT20_UNII 2A






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2021-03418
Page (148) / (376) Pages



ANT2_802.11n_HT20_UNII 2C






ANT2_802.11n_HT20_UNII 3






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2021-03418
Page (149) / (376) Pages



ANT1_802.11ac_VHT20_UNII 1






ANT1_802.11ac_VHT20_UNII 2A






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2021-03418
Page (150) / (376) Pages



ANT1_802.11ac_VHT20_UNII 2C






ANT1_802.11ac_VHT20_UNII 3






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2021-03418
Page (151) / (376) Pages



ANT2_802.11ac_VHT20_UNI1






ANT2_802.11ac_VHT20_UNI1 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (152) / (376) Pages



ANT2_802.11ac_VHT20_UNII 2C






ANT2_802.11ac_VHT20_UNII 3






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (153) / (376) Pages



ANT1_802.11ax_HE20_UNI1 1






ANT1_802.11ax_HE20_UNI1 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (154) / (376) Pages



ANT1_802.11ax_HE20_UNII 2C






ANT1_802.11ax_HE20_UNII 3






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (155) / (376) Pages



ANT2_802.11ax_HE20_UNI 1






ANT2_802.11ax_HE20_UNI 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (156) / (376) Pages



ANT2_802.11ax_HE20_UNII 2C





ANT2_802.11ax_HE20_UNII 3





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501




Report No.:
CTK-2021-03418
Page (157) / (376) Pages



ANT1_802.11n_HT40_UNI I 1



ANT1_802.11n_HT40_UNI I 2A





ANT1_802.11n_HT40_UNI I 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2021-03418
Page (158) / (376) Pages





ANT1_802.11n_HT40_UNI1 3





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501




Report No.:
CTK-2021-03418
Page (159) / (376) Pages



ANT2_802.11n_HT40_UNI I 1



ANT2_802.11n_HT40_UNI I 2A





ANT2_802.11n_HT40_UNI I 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2021-03418
Page (160) / (376) Pages





ANT2_802.11n_HT40_UNI1 3





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2021-03418
 Page (161) / (376) Pages



ANT1_802.11ac_VHT40_UNI1



ANT1_802.11ac_VHT40_UNI1 2A





ANT1_802.11ac_VHT40_UNI1 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2021-03418
Page (162) / (376) Pages





ANT1_802.11ac_VHT40_UNII 3





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2021-03418
 Page (163) / (376) Pages



ANT2_802.11ac_VHT40_UNI1



ANT2_802.11ac_VHT40_UNI1 2A





ANT2_802.11ac_VHT40_UNI1 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2021-03418
Page (164) / (376) Pages





ANT2_802.11ac_VHT40_UNII 3





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2021-03418
 Page (165) / (376) Pages



ANT1_802.11ax_HE40_UNI 1



ANT1_802.11ax_HE40_UNI 2A





ANT1_802.11ax_HE40_UNI 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2021-03418
Page (166) / (376) Pages





ANT1_802.11ax_HE40_UNI 3




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2021-03418
 Page (167) / (376) Pages



ANT2_802.11ax_HE40_UNI 1



ANT2_802.11ax_HE40_UNI 2A





ANT2_802.11ax_HE40_UNI 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2021-03418
Page (168) / (376) Pages



ANT2_802.11ax_HE40_UNI 3