

ANT1_802.11ax_HE20_106T_Low_UNII 2C




ANT1_802.11ax_HE20_106T_Low_UNII 3




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00951
 Page (318) / (659) Pages




ANT1_802.11ax_HE20_106T_Low_UNII 4




ANTO_802.11ax_HE20_106T_High_UNII 1



ANTO_802.11ax_HE20_106T_High_UNII 2A



ANTO_802.11ax_HE20_106T_High_UNI I 2C





ANTO_802.11ax_HE20_106T_High_UNI I 3



CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00951
 Page (321) / (659) Pages






ANTO_802.11ax_HE20_106T_High_UNI I 4





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501



Report No.:
 CTK-2023-00951
 Page (322) / (659) Pages






ANT1_802.11ax_HE20_106T_High_UNII 1



ANT1_802.11ax_HE20_106T_High_UNII 2A



ANT1_802.11ax_HE20_106T_High_UNI I 2C





ANT1_802.11ax_HE20_106T_High_UNI I 3






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-00951
 Page (324) / (659) Pages



ANT1_802.11ax_HE20_106T_High_UNI I 4



ANTO_802.11ax_HE20_242T_UNII 1







ANTO_802.11ax_HE20_242T_UNII 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00951
 Page (326) / (659) Pages



ANTO_802.11ax_HE20_242T_UNII 2C





ANTO_802.11ax_HE20_242T_UNII 3






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-00951
 Page (327) / (659) Pages



ANTO_802.11ax_HE20_242T_UNII 4



ANT1_802.11ax_HE20_242T_UNII 1





ANT1_802.11ax_HE20_242T_UNII 2A





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00951
 Page (329) / (659) Pages



ANT1_802.11ax_HE20_242T_UNII 2C




ANT1_802.11ax_HE20_242T_UNII 3



CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00951
 Page (330) / (659) Pages





ANT1_802.11ax_HE20_242T_UNII 4





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501





Report No.:
 CTK-2023-00951
 Page (331) / (659) Pages



ANTO_802.11n_HT40_UNII 1



ANTO_802.11n_HT40_UNII 2A





ANTO_802.11n_HT40_UNII 2C





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00951
 Page (332) / (659) Pages



ANTO_802.11n_HT40_UNI I 3





ANTO_802.11n_HT40_UNI I 4





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501





Report No.:
 CTK-2023-00951
 Page (333) / (659) Pages



ANT1_802.11n_HT40_UNII 1



ANT1_802.11n_HT40_UNII 2A





ANT1_802.11n_HT40_UNII 2C





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00951
 Page (334) / (659) Pages



ANT1_802.11n_HT40_UNII 3





ANT1_802.11n_HT40_UNII 4





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501





Report No.:
 CTK-2023-00951
 Page (335) / (659) Pages



ANTO_802.11ac_VHT40_UNII 1



ANTO_802.11ac_VHT40_UNII 2A





ANTO_802.11ac_VHT40_UNII 2C





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501



Report No.:
 CTK-2023-00951
 Page (336) / (659) Pages





ANTO_802.11ac_VHT40_UNII 3






ANTO_802.11ac_VHT40_UNII 4



ANT1_802.11ac_VHT40_UNII 1



ANT1_802.11ac_VHT40_UNII 2A





ANT1_802.11ac_VHT40_UNII 2C





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00951
 Page (338) / (659) Pages



ANT1_802.11ac_VHT40_UNII 3





ANT1_802.11ac_VHT40_UNII 4



CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2023-00951
 Page (339) / (659) Pages



ANTO_802.11ax_HE40_26T_Low_UNI 1



ANTO_802.11ax_HE40_26T_Low_UNI 2A





ANTO_802.11ax_HE40_26T_Low_UNI 2C





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501



Report No.:
 CTK-2023-00951
 Page (340) / (659) Pages




ANTO_802.11ax_HE40_26T_Low_UNI 3





ANTO_802.11ax_HE40_26T_Low_UNI 4





ANT1_802.11ax_HE40_26T_Low_UNI 1





ANT1_802.11ax_HE40_26T_Low_UNI 2A



ANT1_802.11ax_HE40_26T_Low_UNI 2C



ANT1_802.11ax_HE40_26T_Low_UNI 3





ANT1_802.11ax_HE40_26T_Low_UNI 4




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501



Report No.:
 CTK-2023-00951
 Page (343) / (659) Pages



ANTO_802.11ax_HE40_26T_Mid_UNII 1



ANTO_802.11ax_HE40_26T_Mid_UNII 2A




ANTO_802.11ax_HE40_26T_Mid_UNII 2C





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501



Report No.:
 CTK-2023-00951
 Page (344) / (659) Pages





ANTO_802.11ax_HE40_26T_Mid_UNI I 3





ANTO_802.11ax_HE40_26T_Mid_UNI I 4



ANT1_802.11ax_HE40_26T_Mid_UNII 1



ANT1_802.11ax_HE40_26T_Mid_UNII 2A





ANT1_802.11ax_HE40_26T_Mid_UNII 2C





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00951
 Page (346) / (659) Pages



ANT1_802.11ax_HE40_26T_Mid_UNI I 3



ANT1_802.11ax_HE40_26T_Mid_UNI I 4




ANTO_802.11ax_HE40_26T_High_UNI 1



ANTO_802.11ax_HE40_26T_High_UNI 2A




ANTO_802.11ax_HE40_26T_High_UNI 2C




ANTO_802.11ax_HE40_26T_High_UNI I 3



ANTO_802.11ax_HE40_26T_High_UNI I 4



ANT1_802.11ax_HE40_26T_High_UNI 1




ANT1_802.11ax_HE40_26T_High_UNI 1A



ANT1_802.11ax_HE40_26T_High_UNI 1C



ANT1_802.11ax_HE40_26T_High_UNI 3





ANT1_802.11ax_HE40_26T_High_UNI 4





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-00951
 Page (351) / (659) Pages



ANTO_802.11ax_HE40_52T_Low_UNI 1



ANTO_802.11ax_HE40_52T_Low_UNI 2A





ANTO_802.11ax_HE40_52T_Low_UNI 2C




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00951
 Page (352) / (659) Pages



ANTO_802.11ax_HE40_52T_Low_UNI 3





ANTO_802.11ax_HE40_52T_Low_UNI 4




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-00951
 Page (353) / (659) Pages




ANT1_802.11ax_HE40_52T_Low_UNI 1




ANT1_802.11ax_HE40_52T_Low_UNI 2A





ANT1_802.11ax_HE40_52T_Low_UNI 2C





ANT1_802.11ax_HE40_52T_Low_UNI 3






ANT1_802.11ax_HE40_52T_Low_UNI 4



ANTO_802.11ax_HE40_52T_Mid_UNII 1



ANTO_802.11ax_HE40_52T_Mid_UNII 2A





ANTO_802.11ax_HE40_52T_Mid_UNII 2C





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00951
 Page (356) / (659) Pages



ANTO_802.11ax_HE40_52T_Mid_UNI I 3



ANTO_802.11ax_HE40_52T_Mid_UNI I 4