







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2023-00951  
 Page (61) / (659) Pages



**ANT1\_802.11n\_HT20\_UNII 1**





**ANT1\_802.11n\_HT20\_UNII 2A**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2023-00951  
 Page (62) / (659) Pages



ANT1\_802.11n\_HT20\_UNII 2C




ANT1\_802.11n\_HT20\_UNII 3



**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2023-00951  
 Page (63) / (659) Pages



ANT1\_802.11n\_HT20\_UNII 4






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2023-00951  
 Page (64) / (659) Pages



**ANTO\_802.11ac\_VHT20\_UNII 1**





**ANTO\_802.11ac\_VHT20\_UNII 2A**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2023-00951  
 Page (65) / (659) Pages



**ANTO\_802.11ac\_VHT20\_UNII 2C**





**ANTO\_802.11ac\_VHT20\_UNII 3**



**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2023-00951  
 Page (66) / (659) Pages




ANTO\_802.11ac\_VHT20\_UNII 4





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2023-00951  
 Page (67) / (659) Pages



**ANT1\_802.11ac\_VHT20\_UNII 1**





**ANT1\_802.11ac\_VHT20\_UNII 2A**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2023-00951  
 Page (68) / (659) Pages



**ANT1\_802.11ac\_VHT20\_UNII 2C**






**ANT1\_802.11ac\_VHT20\_UNII 3**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2023-00951  
 Page (69) / (659) Pages






ANT1\_802.11ac\_VHT20\_UNII 4




**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2023-00951  
 Page (70) / (659) Pages



ANTO\_802.11ax\_HE20\_26T\_Low\_UNII 1






ANTO\_802.11ax\_HE20\_26T\_Low\_UNII 2A




**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2023-00951  
 Page (71) / (659) Pages



**ANTO\_802.11ax\_HE20\_26T\_Low\_UNII 2C**





**ANTO\_802.11ax\_HE20\_26T\_Low\_UNII 3**



**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2023-00951  
 Page (72) / (659) Pages



ANTO\_802.11ax\_HE20\_26T\_Low\_UNI I 4





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2023-00951  
 Page (73) / (659) Pages



ANT1\_802.11ax\_HE20\_26T\_Low\_UNII 1





ANT1\_802.11ax\_HE20\_26T\_Low\_UNII 2A






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2023-00951  
 Page (74) / (659) Pages



**ANT1\_802.11ax\_HE20\_26T\_Low\_UNII 2C**




**ANT1\_802.11ax\_HE20\_26T\_Low\_UNII 3**



**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2023-00951  
 Page (75) / (659) Pages





ANT1\_802.11ax\_HE20\_26T\_Low\_UNI I 4






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2023-00951  
 Page (76) / (659) Pages



**ANTO\_802.11ax\_HE20\_26T\_Mid\_UNII 1**





**ANTO\_802.11ax\_HE20\_26T\_Mid\_UNII 2A**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2023-00951  
 Page (77) / (659) Pages



ANTO\_802.11ax\_HE20\_26T\_Mid\_UNII 2C





ANTO\_802.11ax\_HE20\_26T\_Mid\_UNII 3



**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2023-00951  
 Page (78) / (659) Pages




ANTO\_802.11ax\_HE20\_26T\_Mid\_UNI I 4




**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2023-00951  
 Page (79) / (659) Pages



ANT1\_802.11ax\_HE20\_26T\_Mid\_UNI1 1







ANT1\_802.11ax\_HE20\_26T\_Mid\_UNI1 2A




**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2023-00951  
 Page (80) / (659) Pages



ANT1\_802.11ax\_HE20\_26T\_Mid\_UNI I 2C





ANT1\_802.11ax\_HE20\_26T\_Mid\_UNI I 3



**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2023-00951  
 Page (81) / (659) Pages




ANT1\_802.11ax\_HE20\_26T\_Mid\_UNI I 4





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2023-00951  
 Page (82) / (659) Pages



**ANTO\_802.11ax\_HE20\_26T\_High\_UNI 1**





**ANTO\_802.11ax\_HE20\_26T\_High\_UNI 2A**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2023-00951  
 Page (83) / (659) Pages



**ANTO\_802.11ax\_HE20\_26T\_High\_UNI I 2C**






**ANTO\_802.11ax\_HE20\_26T\_High\_UNI I 3**



**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2023-00951  
 Page (84) / (659) Pages




ANTO\_802.11ax\_HE20\_26T\_High\_UNI I 4





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2023-00951  
 Page (85) / (659) Pages



**ANT1\_802.11ax\_HE20\_26T\_High\_UNI I 1**





**ANT1\_802.11ax\_HE20\_26T\_High\_UNI I 2A**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2023-00951  
 Page (86) / (659) Pages



**ANT1\_802.11ax\_HE20\_26T\_High\_UNI I 2C**





**ANT1\_802.11ax\_HE20\_26T\_High\_UNI I 3**



**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2023-00951  
 Page (87) / (659) Pages





ANT1\_802.11ax\_HE20\_26T\_High\_UNI I 4






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2023-00951  
 Page (88) / (659) Pages



ANTO\_802.11ax\_HE20\_242T\_UNII 1







ANTO\_802.11ax\_HE20\_242T\_UNII 2A





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2023-00951  
 Page (89) / (659) Pages



**ANTO\_802.11ax\_HE20\_242T\_UNII 2C**




**ANTO\_802.11ax\_HE20\_242T\_UNII 3**



**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2023-00951  
 Page (90) / (659) Pages





ANTO\_802.11ax\_HE20\_242T\_UNII 4





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2023-00951  
 Page (91) / (659) Pages



ANT1\_802.11ax\_HE20\_242T\_UNII 1







ANT1\_802.11ax\_HE20\_242T\_UNII 2A






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2023-00951  
 Page (92) / (659) Pages






**ANT1\_802.11ax\_HE20\_242T\_UNII 2C**



**ANT1\_802.11ax\_HE20\_242T\_UNII 3**







ANT1\_802.11ax\_HE20\_242T\_UNII 4




**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501





Report No.:  
 CTK-2023-00951  
 Page (94) / (659) Pages




**ANTO\_802.11n\_HT40\_UNI I 1**




**ANTO\_802.11n\_HT40\_UNI I 2A**





**ANTO\_802.11n\_HT40\_UNI I 2C**




**ANTO\_802.11n\_HT40\_UNII 3**







**ANTO\_802.11n\_HT40\_UNII 4**



**ANT1\_802.11n\_HT40\_UNI I 1**



**ANT1\_802.11n\_HT40\_UNI I 2A**




**ANT1\_802.11n\_HT40\_UNI I 2C**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2023-00951  
 Page (97) / (659) Pages



**ANT1\_802.11n\_HT40\_UNII 3**





**ANT1\_802.11n\_HT40\_UNII 4**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501




Report No.:  
 CTK-2023-00951  
 Page (98) / (659) Pages



**ANTO\_802.11ac\_VHT40\_UNII 1**



**ANTO\_802.11ac\_VHT40\_UNII 2A**





**ANTO\_802.11ac\_VHT40\_UNII 2C**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2023-00951  
 Page (99) / (659) Pages



**ANTO\_802.11ac\_VHT40\_UNII 3**



**ANTO\_802.11ac\_VHT40\_UNII 4**