


ANT1_802.11ax_HE80_52T_Low_UNII 5






ANT1_802.11ax_HE80_52T_Low_UNII 6





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00952
 Page (281) / (427) Pages



ANT1_802.11ax_HE80_52T_Low_UNII 7






ANT1_802.11ax_HE80_52T_Low_UNII 8




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00952
 Page (282) / (427) Pages



ANTO 802.11ax HE80_52T_Mid_UNII 5






ANTO_802.11ax_HE80_52T_Mid_UNII 6





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-00952
 Page (283) / (427) Pages




ANTO_802.11ax_HE80_52T_Mid_UNII 7






ANTO_802.11ax_HE80_52T_Mid_UNII 8





ANT1_802.11ax_HE80_52T_Mid_UNII 5






ANT1_802.11ax_HE80_52T_Mid_UNII 6



ANT1_802.11ax_HE80_52T_Mid_UNII 7



ANT1_802.11ax_HE80_52T_Mid_UNII 8



ANT0_802.11ax_HE80_52T_High_UNII 5






ANT0_802.11ax_HE80_52T_High_UNII 6





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-00952
 Page (287) / (427) Pages




ANTO_802.11ax_HE80_52T_High_UNII 7



ANTO_802.11ax_HE80_52T_High_UNII 8



ANT1_802.11ax_HE80_52T_High_UNII 5






ANT1_802.11ax_HE80_52T_High_UNII 6





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00952
 Page (289) / (427) Pages



ANT1_802.11ax_HE80_52T_High_UNII 7






ANT1_802.11ax_HE80_52T_High_UNII 8




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-00952
 Page (290) / (427) Pages





ANT0_802.11ax_HE80_106T_Low_UNII 5






ANT0_802.11ax_HE80_106T_Low_UNII 6




ANTO_802.11ax_HE80_106T_Low_UNII 7





ANTO_802.11ax_HE80_106T_Low_UNII 8





ANT1_802.11ax_HE80_106T_Low_UNII 5






ANT1_802.11ax_HE80_106T_Low_UNII 6




ANT1_802.11ax_HE80_106T_Low_UNII 7



ANT1_802.11ax_HE80_106T_Low_UNII 8



ANT0_802.11ax_HE80_106T_Mid_UNII 5






ANT0_802.11ax_HE80_106T_Mid_UNII 6





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00952
 Page (295) / (427) Pages



ANT0_802.11ax_HE80_106T_Mid_UNII 7






ANT0_802.11ax_HE80_106T_Mid_UNII 8




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00952
 Page (296) / (427) Pages



ANT1_802.11ax_HE80_106T_Mid_UNII 5






ANT1_802.11ax_HE80_106T_Mid_UNII 6





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-00952
 Page (297) / (427) Pages




ANT1_802.11ax_HE80_106T_Mid_UNII 7



ANT1_802.11ax_HE80_106T_Mid_UNII 8



ANT0_802.11ax_HE80_106T_High_UNII 5






ANT0_802.11ax_HE80_106T_High_UNII 6





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-00952
 Page (299) / (427) Pages




ANTO_802.11ax_HE80_106T_High_UNII 7






ANTO_802.11ax_HE80_106T_High_UNII 8





ANT1_802.11ax_HE80_106T_High_UNII 5






ANT1_802.11ax_HE80_106T_High_UNII 6




ANT1_802.11ax_HE80_106T_High_UNII 7






ANT1_802.11ax_HE80_106T_High_UNII 8





ANT0_802.11ax_HE80_242T_Low_UNII 5






ANT0_802.11ax_HE80_242T_Low_UNII 6




ANTO_802.11ax_HE80_242T_Low_UNII 7






ANTO_802.11ax_HE80_242T_Low_UNII 8





ANT1_802.11ax_HE80_242T_Low_UNII 5






ANT1_802.11ax_HE80_242T_Low_UNII 6




ANT1_802.11ax_HE80_242T_Low_UNII 7






ANT1_802.11ax_HE80_242T_Low_UNII 8





ANT0_802.11ax_HE80_242T_Mid_UNII 5






ANT0_802.11ax_HE80_242T_Mid_UNII 6




ANT0_802.11ax_HE80_242T_Mid_UNII 7



ANT0_802.11ax_HE80_242T_Mid_UNII 8



ANT1_802.11ax_HE80_242T_Mid_UNII 5






ANT1_802.11ax_HE80_242T_Mid_UNII 6





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-00952
 Page (309) / (427) Pages




ANT1_802.11ax_HE80_242T_Mid_UNII 7



ANT1_802.11ax_HE80_242T_Mid_UNII 8



ANT0_802.11ax_HE80_242T_High_UNII 5






ANT0_802.11ax_HE80_242T_High_UNII 6





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-00952
 Page (311) / (427) Pages




ANTO_802.11ax_HE80_242T_High_UNII 7



ANTO_802.11ax_HE80_242T_High_UNII 8



ANT1_802.11ax_HE80_242T_High_UNII 5






ANT1_802.11ax_HE80_242T_High_UNII 6





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00952
 Page (313) / (427) Pages



ANT1_802.11ax_HE80_242T_High_UNII 7






ANT1_802.11ax_HE80_242T_High_UNII 8




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00952
 Page (314) / (427) Pages



ANT0_802.11ax_HE80_484T_Low_UNII 5



ANT0_802.11ax_HE80_484T_Low_UNII 6