



ANTO_802.11ax_HE40_106T_High_UNII 5






ANTO_802.11ax_HE40_106T_High_UNII 6






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-00952
 Page (251) / (427) Pages





ANTO_802.11ax_HE40_106T_High_UNII 7






ANTO_802.11ax_HE40_106T_High_UNII 8






ANT1_802.11ax_HE40_106T_High_UNII 5



ANT1_802.11ax_HE40_106T_High_UNII 6



ANT1_802.11ax_HE40_106T_High_UNII 7






ANT1_802.11ax_HE40_106T_High_UNII 8





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00952
 Page (254) / (427) Pages



ANTO_802.11ax_HE40_242T_Low_UNII 5






ANTO_802.11ax_HE40_242T_Low_UNII 6






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-00952
 Page (255) / (427) Pages





ANT0_802.11ax_HE40_242T_Low_UNII 7






ANT0_802.11ax_HE40_242T_Low_UNII 8






ANT1_802.11ax_HE40_242T_Low_UNII 5






ANT1_802.11ax_HE40_242T_Low_UNII 6





ANT1_802.11ax_HE40_242T_Low_UNII 7



ANT1_802.11ax_HE40_242T_Low_UNII 8



ANTO_802.11ax_HE40_242T_High_UNII 5






ANTO_802.11ax_HE40_242T_High_UNII 6






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00952
 Page (259) / (427) Pages



ANTO_802.11ax_HE40_242T_High_UNII 7






ANTO_802.11ax_HE40_242T_High_UNII 8





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00952
 Page (260) / (427) Pages



ANT1_802.11ax_HE40_242T_High_UNII 5






ANT1_802.11ax_HE40_242T_High_UNII 6






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-00952
 Page (261) / (427) Pages





ANT1_802.11ax_HE40_242T_High_UNII 7



ANT1_802.11ax_HE40_242T_High_UNII 8



ANTO_802.11ax_HE40_484T_UNII 5






ANTO_802.11ax_HE40_484T_UNII 6






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-00952
 Page (263) / (427) Pages





ANTO_802.11ax_HE40_484T_UNII 7



ANTO_802.11ax_HE40_484T_UNII 8



ANT1_802.11ax_HE40_484T_UNII 5






ANT1_802.11ax_HE40_484T_UNII 6






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00952
 Page (265) / (427) Pages



ANT1_802.11ax_HE40_484T_UNII 7






ANT1_802.11ax_HE40_484T_UNII 8




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501



Report No.:
 CTK-2023-00952
 Page (266) / (427) Pages





ANT0_802.11ax_HE80_26T_Low_UNII 5



ANT0_802.11ax_HE80_26T_Low_UNII 6



ANT0_802.11ax_HE80_26T_Low_UNII 7






ANT0_802.11ax_HE80_26T_Low_UNII 8



CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00952
 Page (268) / (427) Pages



ANT1_802.11ax_HE80_26T_Low_UNII 5





ANT1_802.11ax_HE80_26T_Low_UNII 6





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-00952
 Page (269) / (427) Pages




ANT1_802.11ax_HE80_26T_Low_UNII 7






ANT1_802.11ax_HE80_26T_Low_UNII 8





ANTO 802.11ax HE80 26T Mid UNII 5






ANTO_802.11ax_HE80_26T_Mid_UNII 6




ANTO_802.11ax_HE80_26T_Mid_UNII 7






ANTO_802.11ax_HE80_26T_Mid_UNII 8





ANT1_802.11ax_HE80_26T_Mid_UNII 5






ANT1_802.11ax_HE80_26T_Mid_UNII 6




ANT1_802.11ax_HE80_26T_Mid_UNII 7



ANT1_802.11ax_HE80_26T_Mid_UNII 8



ANTO_802.11ax_HE80_26T_High_UNII 5






ANTO_802.11ax_HE80_26T_High_UNII 6





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-00952
 Page (275) / (427) Pages




ANTO_802.11ax_HE80_26T_High_UNII 7



ANTO_802.11ax_HE80_26T_High_UNII 8



ANT1_802.11ax_HE80_26T_High_UNII 5






ANT1_802.11ax_HE80_26T_High_UNII 6





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-00952
 Page (277) / (427) Pages




ANT1_802.11ax_HE80_26T_High_UNII 7






ANT1_802.11ax_HE80_26T_High_UNII 8





ANT0_802.11ax_HE80_52T_Low_UNII 5



ANT0_802.11ax_HE80_52T_Low_UNII 6



ANTO_802.11ax_HE80_52T_Low_UNII 7



ANTO_802.11ax_HE80_52T_Low_UNII 8