




ANT1_802.11ax_HE20_52T_Mid_UNII 5






ANT1_802.11ax_HE20_52T_Mid_UNII 6







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00952
 Page (201) / (427) Pages



ANT1_802.11ax_HE20_52T_Mid_UNII 7






ANT1_802.11ax_HE20_52T_Mid_UNII 8






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00952
 Page (202) / (427) Pages



ANTO_802.11ax_HE20_52T_High_UNII 5






ANTO_802.11ax_HE20_52T_High_UNII 6







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-00952
 Page (203) / (427) Pages






ANT0_802.11ax_HE20_52T_High_UNII 7



ANT0_802.11ax_HE20_52T_High_UNII 8



ANT1_802.11ax_HE20_52T_High_UNII 5






ANT1_802.11ax_HE20_52T_High_UNII 6







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00952
 Page (205) / (427) Pages



ANT1_802.11ax_HE20_52T_High_UNII 7






ANT1_802.11ax_HE20_52T_High_UNII 8






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00952
 Page (206) / (427) Pages



ANT0_802.11ax_HE20_106T_Low_UNII 5






ANT0_802.11ax_HE20_106T_Low_UNII 6







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00952
 Page (207) / (427) Pages



ANTO_802.11ax_HE20_106T_Low_UNII 7






ANTO_802.11ax_HE20_106T_Low_UNII 8






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00952
 Page (208) / (427) Pages



ANT1_802.11ax_HE20_106T_Low_UNII 5






ANT1_802.11ax_HE20_106T_Low_UNII 6







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00952
 Page (209) / (427) Pages



ANT1_802.11ax_HE20_106T_Low_UNII 7






ANT1_802.11ax_HE20_106T_Low_UNII 8






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00952
 Page (210) / (427) Pages



ANT0_802.11ax_HE20_106T_High_UNII 5






ANT0_802.11ax_HE20_106T_High_UNII 6







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00952
 Page (211) / (427) Pages



ANTO_802.11ax_HE20_106T_High_UNII 7






ANTO_802.11ax_HE20_106T_High_UNII 8






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00952
 Page (212) / (427) Pages



ANT1_802.11ax_HE20_106T_High_UNII 5






ANT1_802.11ax_HE20_106T_High_UNII 6







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-00952
 Page (213) / (427) Pages






ANT1_802.11ax_HE20_106T_High_UNII 7



ANT1_802.11ax_HE20_106T_High_UNII 8



ANTO_802.11ax_HE20_242T_UNII 5






ANTO_802.11ax_HE20_242T_UNII 6







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-00952
 Page (215) / (427) Pages






ANTO_802.11ax_HE20_242T_UNII 7



ANTO_802.11ax_HE20_242T_UNII 8



ANT1_802.11ax_HE20_242T_UNII 5






ANT1_802.11ax_HE20_242T_UNII 6







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00952
 Page (217) / (427) Pages



ANT1_802.11ax_HE20_242T_UNII 7






ANT1_802.11ax_HE20_242T_UNII 8





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00952
 Page (218) / (427) Pages



ANT0_802.11ax_HE40_26T_Low_UNII 5






ANT0_802.11ax_HE40_26T_Low_UNII 6






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-00952
 Page (219) / (427) Pages





ANT0_802.11ax_HE40_26T_Low_UNII 7






ANT0_802.11ax_HE40_26T_Low_UNII 8






ANT1_802.11ax_HE40_26T_Low_UNII 5






ANT1_802.11ax_HE40_26T_Low_UNII 6





ANT1_802.11ax_HE40_26T_Low_UNII 7



ANT1_802.11ax_HE40_26T_Low_UNII 8



ANTO_802.11ax_HE40_26T_Mid_UNII 5



ANTO_802.11ax_HE40_26T_Mid_UNII 6