







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501





Report No.:  
 CTK-2023-01326  
 Page (300) / (539) Pages



**ANT R\_802.11ax\_HE40\_106T\_Mid\_UNII 1**



**ANT R\_802.11ax\_HE40\_106T\_Mid\_UNII 2A**





**ANT R\_802.11ax\_HE40\_106T\_Mid\_UNII 2C**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2023-01326  
 Page (301) / (539) Pages







**ANT R\_802.11ax\_HE40\_106T\_Mid\_UNII 3**



**ANT L\_802.11ax\_HE40\_106T\_High\_UNII 1**



**ANT L\_802.11ax\_HE40\_106T\_High\_UNII 2A**





**ANT L\_802.11ax\_HE40\_106T\_High\_UNII 2C**



**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2023-01326  
 Page (303) / (539) Pages





**ANT L\_802.11ax\_HE40\_106T\_High\_UNII 3**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501





Report No.:  
 CTK-2023-01326  
 Page (304) / (539) Pages



**ANT R\_802.11ax\_HE40\_106T\_High\_UNII 1**



**ANT R\_802.11ax\_HE40\_106T\_High\_UNII 2A**





**ANT R\_802.11ax\_HE40\_106T\_High\_UNII 2C**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2023-01326  
 Page (305) / (539) Pages







**ANT\_R\_802.11ax\_HE40\_106T\_High\_UNII 3**



**ANT L\_802.11ax\_HE40\_242T\_Low\_UNII 1**



**ANT L\_802.11ax\_HE40\_242T\_Low\_UNII 2A**





**ANT L\_802.11ax\_HE40\_242T\_Low\_UNII 2C**



**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2023-01326  
 Page (307) / (539) Pages





**ANT L\_802.11ax\_HE40\_242T\_Low\_UNII 3**







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501





Report No.:  
 CTK-2023-01326  
 Page (308) / (539) Pages



**ANT R\_802.11ax\_HE40\_242T\_Low\_UNII 1**



**ANT R\_802.11ax\_HE40\_242T\_Low\_UNII 2A**





**ANT R\_802.11ax\_HE40\_242T\_Low\_UNII 2C**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2023-01326  
 Page (309) / (539) Pages







**ANT R\_802.11ax\_HE40\_242T\_Low\_UNII 3**



**ANT L\_802.11ax\_HE40\_242T\_High\_UNII 1**



**ANT L\_802.11ax\_HE40\_242T\_High\_UNII 2A**





**ANT L\_802.11ax\_HE40\_242T\_High\_UNII 2C**



**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2023-01326  
 Page (311) / (539) Pages





**ANT L\_802.11ax\_HE40\_242T\_High\_UNII 3**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501





Report No.:  
 CTK-2023-01326  
 Page (312) / (539) Pages



**ANT R\_802.11ax\_HE40\_242T\_High\_UNII 1**



**ANT R\_802.11ax\_HE40\_242T\_High\_UNII 2A**





**ANT R\_802.11ax\_HE40\_242T\_High\_UNII 2C**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2023-01326  
 Page (313) / (539) Pages







**ANT\_R\_802.11ax\_HE40\_242T\_High\_UNII 3**



**ANT L\_802.11ax\_HE40\_484T\_UNII 1**



**ANT L\_802.11ax\_HE40\_484T\_UNII 2A**





**ANT L\_802.11ax\_HE40\_484T\_UNII 2C**



**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2023-01326  
 Page (315) / (539) Pages





**ANT L\_802.11ax\_HE40\_484T\_UNII 3**







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501





Report No.:  
 CTK-2023-01326  
 Page (316) / (539) Pages



**ANT R\_802.11ax\_HE40\_484T\_UNII 1**



**ANT R\_802.11ax\_HE40\_484T\_UNII 2A**





**ANT R\_802.11ax\_HE40\_484T\_UNII 2C**




**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2023-01326  
 Page (317) / (539) Pages






**ANT R\_802.11ax\_HE40\_484T\_UNII 3**




**ANT L\_802.11ac\_VHT80\_UNII 1**




**ANT L\_802.11ac\_VHT80\_UNII 2A**




**ANT L\_802.11ac\_VHT80\_UNII 2C**






**ANT L\_802.11ac\_VHT80\_UNII 3**




**ANT R\_802.11ac\_VHT80\_UNII 1**



**ANT R\_802.11ac\_VHT80\_UNII 2A**



**ANT R\_802.11ac\_VHT80\_UNII 2C**




**ANT R\_802.11ac\_VHT80\_UNII 3**




**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2023-01326  
 Page (320) / (539) Pages




ANT L\_802.11ax\_HE80\_26T\_Low\_UNII 1



ANT L\_802.11ax\_HE80\_26T\_Low\_UNII 2A



ANT L\_802.11ax\_HE80\_26T\_Low\_UNII 2C




ANT L\_802.11ax\_HE80\_26T\_Low\_UNII 3




**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2023-01326  
 Page (321) / (539) Pages




ANT R\_802.11ax\_HE80\_26T\_Low\_UNII 1



ANT R\_802.11ax\_HE80\_26T\_Low\_UNII 2A



ANT R\_802.11ax\_HE80\_26T\_Low\_UNII 2C




ANT R\_802.11ax\_HE80\_26T\_Low\_UNII 3




**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501




Report No.:  
 CTK-2023-01326  
 Page (322) / (539) Pages




ANT L\_802.11ax\_HE80\_26T\_Mid\_UNII 1



ANT L\_802.11ax\_HE80\_26T\_Mid\_UNII 2A



ANT L\_802.11ax\_HE80\_26T\_Mid\_UNII 2C




ANT L\_802.11ax\_HE80\_26T\_Mid\_UNII 3




**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501




Report No.:  
 CTK-2023-01326  
 Page (323) / (539) Pages




ANT R\_802.11ax\_HE80\_26T\_Mid\_UNII 1



ANT R\_802.11ax\_HE80\_26T\_Mid\_UNII 2A



ANT R\_802.11ax\_HE80\_26T\_Mid\_UNII 2C




ANT R\_802.11ax\_HE80\_26T\_Mid\_UNII 3






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2023-01326  
 Page (324) / (539) Pages





ANT L\_802.11ax\_HE80\_26T\_High\_UNII 1



ANT L\_802.11ax\_HE80\_26T\_High\_UNII 2A



ANT L\_802.11ax\_HE80\_26T\_High\_UNII 2C




ANT L\_802.11ax\_HE80\_26T\_High\_UNII 3




**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2023-01326  
 Page (325) / (539) Pages





**ANT R\_802.11ax\_HE80\_26T\_High\_UNII 1**



**ANT R\_802.11ax\_HE80\_26T\_High\_UNII 2A**



**ANT R\_802.11ax\_HE80\_26T\_High\_UNII 2C**




**ANT R\_802.11ax\_HE80\_26T\_High\_UNII 3**




**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2023-01326  
 Page (326) / (539) Pages




ANT L\_802.11ax\_HE80\_52T\_Low\_UNII 1



ANT L\_802.11ax\_HE80\_52T\_Low\_UNII 2A



ANT L\_802.11ax\_HE80\_52T\_Low\_UNII 2C




ANT L\_802.11ax\_HE80\_52T\_Low\_UNII 3




**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501




Report No.:  
 CTK-2023-01326  
 Page (327) / (539) Pages




ANT R\_802.11ax\_HE80\_52T\_Low\_UNII 1



ANT R\_802.11ax\_HE80\_52T\_Low\_UNII 2A



ANT R\_802.11ax\_HE80\_52T\_Low\_UNII 2C



ANT R\_802.11ax\_HE80\_52T\_Low\_UNII 3