




ANT L_802.11ax_HE20_52T_High_UNII 1







ANT L_802.11ax_HE20_52T_High_UNII 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-01326
 Page (247) / (539) Pages



ANT L_802.11ax_HE20_52T_High_UNII 2C






ANT L_802.11ax_HE20_52T_High_UNII 3






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-01326
 Page (248) / (539) Pages



ANT R_802.11ax_HE20_52T_High_UNII 1







ANT R_802.11ax_HE20_52T_High_UNII 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-01326
 Page (249) / (539) Pages



ANT R_802.11ax_HE20_52T_High_UNII 2C






ANT R_802.11ax_HE20_52T_High_UNII 3






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-01326
 Page (250) / (539) Pages



ANT L_802.11ax_HE20_106T_Low_UNII 1







ANT L_802.11ax_HE20_106T_Low_UNII 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-01326
 Page (251) / (539) Pages



ANT L_802.11ax_HE20_106T_Low_UNII 2C






ANT L_802.11ax_HE20_106T_Low_UNII 3






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-01326
 Page (252) / (539) Pages



ANT R_802.11ax_HE20_106T_Low_UNII 1







ANT R_802.11ax_HE20_106T_Low_UNII 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-01326
 Page (253) / (539) Pages



ANT R_802.11ax_HE20_106T_Low_UNII 2C






ANT R_802.11ax_HE20_106T_Low_UNII 3






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-01326
 Page (254) / (539) Pages



ANT L_802.11ax_HE20_106T_High_UNII 1







ANT L_802.11ax_HE20_106T_High_UNII 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-01326
 Page (255) / (539) Pages






ANT L_802.11ax_HE20_106T_High_UNII 2C



ANT L_802.11ax_HE20_106T_High_UNII 3



ANT R_802.11ax_HE20_106T_High_UNII 1







ANT R_802.11ax_HE20_106T_High_UNII 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-01326
 Page (257) / (539) Pages






ANT R_802.11ax_HE20_106T_High_UNII 2C



ANT R_802.11ax_HE20_106T_High_UNII 3



ANT L_802.11ax_HE20_242T_UNII 1







ANT L_802.11ax_HE20_242T_UNII 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-01326
 Page (259) / (539) Pages



ANT L_802.11ax_HE20_242T_UNII 2C






ANT L_802.11ax_HE20_242T_UNII 3






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-01326
 Page (260) / (539) Pages



ANT R_802.11ax_HE20_242T_UNII 1







ANT R_802.11ax_HE20_242T_UNII 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-01326
 Page (261) / (539) Pages



ANT R_802.11ax_HE20_242T_UNII 2C





ANT R_802.11ax_HE20_242T_UNII 3





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501





Report No.:
 CTK-2023-01326
 Page (262) / (539) Pages



ANT L_802.11n_HT40_UNII 1



ANT L_802.11n_HT40_UNII 2A





ANT L_802.11n_HT40_UNII 2C



CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-01326
 Page (263) / (539) Pages





ANT L_802.11n_HT40_UNII 3





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501





Report No.:
 CTK-2023-01326
 Page (264) / (539) Pages



ANT R_802.11n_HT40_UNII 1



ANT R_802.11n_HT40_UNII 2A





ANT R_802.11n_HT40_UNII 2C





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501



Report No.:
 CTK-2023-01326
 Page (265) / (539) Pages







ANT R_802.11n_HT40_UNII 3



ANT L_802.11ac_VHT40_UNII 1



ANT L_802.11ac_VHT40_UNII 2A





ANT L_802.11ac_VHT40_UNII 2C



CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-01326
 Page (267) / (539) Pages





ANT L_802.11ac_VHT40_UNII 3





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501





Report No.:
 CTK-2023-01326
 Page (268) / (539) Pages



ANT R_802.11ac_VHT40_UNII 1



ANT R_802.11ac_VHT40_UNII 2A





ANT R_802.11ac_VHT40_UNII 2C



CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-01326
 Page (269) / (539) Pages



ANT R_802.11ac_VHT40_UNII 3