




ANT R_802.11ac_VHT20_UNII 1







ANT R_802.11ac_VHT20_UNII 2A





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2023-01326
 Page (225) / (539) Pages






ANT R_802.11ac_VHT20_UNII 2C






ANT R_802.11ac_VHT20_UNII 3





ANT L_802.11ax_HE20_26T_Low_UNII 1







ANT L_802.11ax_HE20_26T_Low_UNII 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-01326
 Page (227) / (539) Pages






ANT L_802.11ax_HE20_26T_Low_UNII 2C



ANT L_802.11ax_HE20_26T_Low_UNII 3



ANT R_802.11ax_HE20_26T_Low_UNII 1







ANT R_802.11ax_HE20_26T_Low_UNII 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-01326
 Page (229) / (539) Pages






ANT R_802.11ax_HE20_26T_Low_UNII 2C



ANT R_802.11ax_HE20_26T_Low_UNII 3



ANT L_802.11ax_HE20_26T_Mid_UNII 1







ANT L_802.11ax_HE20_26T_Mid_UNII 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-01326
 Page (231) / (539) Pages



ANT L_802.11ax_HE20_26T_Mid_UNII 2C






ANT L_802.11ax_HE20_26T_Mid_UNII 3






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-01326
 Page (232) / (539) Pages



ANT R_802.11ax_HE20_26T_Mid_UNII 1







ANT R_802.11ax_HE20_26T_Mid_UNII 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-01326
 Page (233) / (539) Pages






ANT R_802.11ax_HE20_26T_Mid_UNII 2C



ANT R_802.11ax_HE20_26T_Mid_UNII 3



ANT L_802.11ax_HE20_26T_High_UNII 1







ANT L_802.11ax_HE20_26T_High_UNII 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-01326
 Page (235) / (539) Pages



ANT L_802.11ax_HE20_26T_High_UNII 2C






ANT L_802.11ax_HE20_26T_High_UNII 3






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-01326
 Page (236) / (539) Pages



ANT R_802.11ax_HE20_26T_High_UNII 1







ANT R_802.11ax_HE20_26T_High_UNII 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-01326
 Page (237) / (539) Pages



ANT R_802.11ax_HE20_26T_High_UNII 2C






ANT R_802.11ax_HE20_26T_High_UNII 3






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-01326
 Page (238) / (539) Pages



ANT L_802.11ax_HE20_52T_Low_UNII 1







ANT L_802.11ax_HE20_52T_Low_UNII 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-01326
 Page (239) / (539) Pages






ANT L_802.11ax_HE20_52T_Low_UNII 2C



ANT L_802.11ax_HE20_52T_Low_UNII 3



ANT R_802.11ax_HE20_52T_Low_UNII 1







ANT R_802.11ax_HE20_52T_Low_UNII 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-01326
 Page (241) / (539) Pages



ANT R_802.11ax_HE20_52T_Low_UNII 2C






ANT R_802.11ax_HE20_52T_Low_UNII 3






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-01326
 Page (242) / (539) Pages



ANT L_802.11ax_HE20_52T_Mid_UNII 1







ANT L_802.11ax_HE20_52T_Mid_UNII 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-01326
 Page (243) / (539) Pages



ANT L_802.11ax_HE20_52T_Mid_UNII 2C






ANT L_802.11ax_HE20_52T_Mid_UNII 3






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-01326
 Page (244) / (539) Pages



ANT R_802.11ax_HE20_52T_Mid_UNII 1







ANT R_802.11ax_HE20_52T_Mid_UNII 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-01326
 Page (245) / (539) Pages



ANT R_802.11ax_HE20_52T_Mid_UNII 2C



ANT R_802.11ax_HE20_52T_Mid_UNII 3