







ANT L_802.11ax_HE80_52T_Mid_UNII 5



ANT L_802.11ax_HE80_52T_Mid_UNII 6



ANT L_802.11ax_HE80_52T_Mid_UNII 7






ANT L_802.11ax_HE80_52T_Mid_UNII 8




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-01432
 Page (284) / (427) Pages





ANT_R_802.11ax_HE80_52T_Mid_UNII 5



ANT_R_802.11ax_HE80_52T_Mid_UNII 6



ANT R_802.11ax_HE80_52T_Mid_UNII 7






ANT R_802.11ax_HE80_52T_Mid_UNII 8




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-01432
 Page (286) / (427) Pages





ANT L_802.11ax_HE80_52T_High_UNII 5



ANT L_802.11ax_HE80_52T_High_UNII 6



ANT L_802.11ax_HE80_52T_High_UNII 7






ANT L_802.11ax_HE80_52T_High_UNII 8




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-01432
 Page (288) / (427) Pages





ANT R_802.11ax_HE80_52T_High_UNII 5






ANT R_802.11ax_HE80_52T_High_UNII 6



ANT R_802.11ax_HE80_52T_High_UNII 7





ANT R_802.11ax_HE80_52T_High_UNII 8





ANT L_802.11ax_HE80_106T_Low_UNII 5



ANT L_802.11ax_HE80_106T_Low_UNII 6



ANT L_802.11ax_HE80_106T_Low_UNII 7





ANT L_802.11ax_HE80_106T_Low_UNII 8




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-01432
 Page (292) / (427) Pages





ANT R_802.11ax_HE80_106T_Low_UNII 5






ANT R_802.11ax_HE80_106T_Low_UNII 6




ANT R_802.11ax_HE80_106T_Low_UNII 7






ANT R_802.11ax_HE80_106T_Low_UNII 8





ANT L_802.11ax_HE80_106T_Mid_UNII 5



ANT L_802.11ax_HE80_106T_Mid_UNII 6



ANT L_802.11ax_HE80_106T_Mid_UNII 7






ANT L_802.11ax_HE80_106T_Mid_UNII 8




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-01432
 Page (296) / (427) Pages





ANT R_802.11ax_HE80_106T_Mid_UNII 5



ANT R_802.11ax_HE80_106T_Mid_UNII 6



ANT R_802.11ax_HE80_106T_Mid_UNII 7






ANT R_802.11ax_HE80_106T_Mid_UNII 8




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-01432
 Page (298) / (427) Pages





ANT L_802.11ax_HE80_106T_High_UNII 5



ANT L_802.11ax_HE80_106T_High_UNII 6



ANT L_802.11ax_HE80_106T_High_UNII 7






ANT L_802.11ax_HE80_106T_High_UNII 8




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-01432
 Page (300) / (427) Pages





ANT R_802.11ax_HE80_106T_High_UNII 5






ANT R_802.11ax_HE80_106T_High_UNII 6




ANT R_802.11ax_HE80_106T_High_UNII 7






ANT R_802.11ax_HE80_106T_High_UNII 8





ANT L_802.11ax_HE80_242T_Low_UNII 5






ANT L_802.11ax_HE80_242T_Low_UNII 6




ANT L_802.11ax_HE80_242T_Low_UNII 7






ANT L_802.11ax_HE80_242T_Low_UNII 8





ANT R_802.11ax_HE80_242T_Low_UNII 5



ANT R_802.11ax_HE80_242T_Low_UNII 6



ANT R_802.11ax_HE80_242T_Low_UNII 7






ANT R_802.11ax_HE80_242T_Low_UNII 8




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-01432
 Page (306) / (427) Pages





ANT L_802.11ax_HE80_242T_Mid_UNII 5



ANT L_802.11ax_HE80_242T_Mid_UNII 6



ANT L_802.11ax_HE80_242T_Mid_UNII 7






ANT L_802.11ax_HE80_242T_Mid_UNII 8




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-01432
 Page (308) / (427) Pages





ANT R_802.11ax_HE80_242T_Mid_UNII 5






ANT R_802.11ax_HE80_242T_Mid_UNII 6




ANT R_802.11ax_HE80_242T_Mid_UNII 7






ANT R_802.11ax_HE80_242T_Mid_UNII 8





ANT L_802.11ax_HE80_242T_High_UNII 5






ANT L_802.11ax_HE80_242T_High_UNII 6




ANT L_802.11ax_HE80_242T_High_UNII 7






ANT L_802.11ax_HE80_242T_High_UNII 8





ANT R_802.11ax_HE80_242T_High_UNII 5






ANT R_802.11ax_HE80_242T_High_UNII 6




ANT R_802.11ax_HE80_242T_High_UNII 7



ANT R_802.11ax_HE80_242T_High_UNII 8



ANT L_802.11ax_HE80_484T_Low_UNII 5



ANT L_802.11ax_HE80_484T_Low_UNII 6