









ANT R_802.11ax_HE40_106T_High_UNII 5






ANT R_802.11ax_HE40_106T_High_UNII 6





ANT R_802.11ax_HE40_106T_High_UNII 7






ANT R_802.11ax_HE40_106T_High_UNII 8






ANT L_802.11ax_HE40_242T_Low_UNII 5






ANT L_802.11ax_HE40_242T_Low_UNII 6





ANT L_802.11ax_HE40_242T_Low_UNII 7






ANT L_802.11ax_HE40_242T_Low_UNII 8






ANT R_802.11ax_HE40_242T_Low_UNII 5






ANT R_802.11ax_HE40_242T_Low_UNII 6





ANT R_802.11ax_HE40_242T_Low_UNII 7






ANT R_802.11ax_HE40_242T_Low_UNII 8






ANT L_802.11ax_HE40_242T_High_UNII 5






ANT L_802.11ax_HE40_242T_High_UNII 6





ANT L_802.11ax_HE40_242T_High_UNII 7






ANT L_802.11ax_HE40_242T_High_UNII 8






ANT R_802.11ax_HE40_242T_High_UNII 5






ANT R_802.11ax_HE40_242T_High_UNII 6





ANT R_802.11ax_HE40_242T_High_UNII 7






ANT R_802.11ax_HE40_242T_High_UNII 8






ANT L_802.11ax_HE40_484T_UNII 5






ANT L_802.11ax_HE40_484T_UNII 6





ANT L_802.11ax_HE40_484T_UNII 7






ANT L_802.11ax_HE40_484T_UNII 8






ANT R_802.11ax_HE40_484T_UNII 5



ANT R_802.11ax_HE40_484T_UNII 6



ANT R_802.11ax_HE40_484T_UNII 7






ANT R_802.11ax_HE40_484T_UNII 8



CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501



Report No.:
 CTK-2023-01432
 Page (266) / (427) Pages





ANT L_802.11ax_HE80_26T_Low_UNII 5



ANT L_802.11ax_HE80_26T_Low_UNII 6



ANT L_802.11ax_HE80_26T_Low_UNII 7






ANT L_802.11ax_HE80_26T_Low_UNII 8



CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-01432
 Page (268) / (427) Pages





ANT R_802.11ax_HE80_26T_Low_UNII 5






ANT R_802.11ax_HE80_26T_Low_UNII 6




ANT R_802.11ax_HE80_26T_Low_UNII 7






ANT R_802.11ax_HE80_26T_Low_UNII 8





ANT L_802.11ax_HE80_26T_Mid_UNII 5



ANT L_802.11ax_HE80_26T_Mid_UNII 6



ANT L_802.11ax_HE80_26T_Mid_UNII 7






ANT L_802.11ax_HE80_26T_Mid_UNII 8




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-01432
 Page (272) / (427) Pages





ANT_R_802.11ax_HE80_26T_Mid_UNII 5



ANT_R_802.11ax_HE80_26T_Mid_UNII 6



ANT R_802.11ax_HE80_26T_Mid_UNII 7






ANT R_802.11ax_HE80_26T_Mid_UNII 8




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-01432
 Page (274) / (427) Pages





ANT L_802.11ax_HE80_26T_High_UNII 5



ANT L_802.11ax_HE80_26T_High_UNII 6



ANT L_802.11ax_HE80_26T_High_UNII 7






ANT L_802.11ax_HE80_26T_High_UNII 8




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-01432
 Page (276) / (427) Pages





ANT R_802.11ax_HE80_26T_High_UNII 5



ANT R_802.11ax_HE80_26T_High_UNII 6



ANT R_802.11ax_HE80_26T_High_UNII 7






ANT R_802.11ax_HE80_26T_High_UNII 8




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501



Report No.:
 CTK-2023-01432
 Page (278) / (427) Pages





ANT L_802.11ax_HE80_52T_Low_UNII 5



ANT L_802.11ax_HE80_52T_Low_UNII 6



ANT L_802.11ax_HE80_52T_Low_UNII 7






ANT L_802.11ax_HE80_52T_Low_UNII 8




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-01432
 Page (280) / (427) Pages





ANT R_802.11ax_HE80_52T_Low_UNII 5



ANT R_802.11ax_HE80_52T_Low_UNII 6



ANT R_802.11ax_HE80_52T_Low_UNII 7



ANT R_802.11ax_HE80_52T_Low_UNII 8