






D

C

B


A

D


C

B

A












VALUE	X0601	X1411	R0603	R0602	C0601	R0605	R0608	C0628	C0629	C0630
Crystal	TCXO	SMT	NC	SMT	NC	NC	SMT	NC	SMT	NC
	NC	TCXO	NC	SMT	NC	SMT	NC	NC	SMT	SMT








DRAWN:	<Drawn By>	DATED:	<Drawn Date>
CHECKED:	<Checked By>	DATED:	<Checked Date>
QUALITY CONTROL:	<QC By>	DATED:	<QC Date>
RELEASED:	<Released By>	DATED:	<Release Date>

COMPANY: <Company Name>			
TITLE: <Title>			
CODE: <Code>	SIZE: A1	DRAWING NO: <Drawing Number>	REV: <Revision>
SCALE: <Scale>			
SHEET: 6F 20			



COMPANY:		<Company Name>	
TITLE:		<Title>	
CODE:	SIZE:	DRAWING NO:	REV:
<Code>	A1	<Drawing Number>	<Revision>
SCALE: <Scale>		SHEET: 26	20





DRAWN: <Drawn By>	DATED: <Drawn Date>
CHECKED: <Checked By>	DATED: <Checked Date>
QUALITY CONTROL: <QC By>	DATED: <QC Date>
RELEASED: <Released By>	DATED: <Release Date>

COMPANY: <Company Name>			
TITLE: <Title>			
CODE: <Code>	SIZE: A1	DRAWING NO: <Drawing Number>	REV: <Revision>
SCALE: <Scale>		SHEET: 1 of 20	