



ADMINISTRATIVE CENTER ■ 2000 NORTH M 63 ■ BENTON HARBOR, MI 49022

Bill Stumpf
D.L.S. Electronic Systems, Inc.
166 South Carter Street
Genoa City WI 53128

Bill,

Whirlpool is utilizing only the 2.4 GHz WIFI portion of the Marvell 8787 radio. The 5GHz, Bluetooth, and FM antenna pins are not connected to antennas. Further the software for Bluetooth and FM has been removed from the radio software driver. And the Driver has single band operation selected at 2.4GHz. The driver file is revision controlled by Whirlpool. There is no other way to modify these parameters in the field, through service, through the application software, or at our Whirlpool Factories.

A handwritten signature in cursive script that reads "Ray Russell".

Ray Russell
Whirlpool Corporation
Research & Engineering Center
750 East Monte Road, MD 5210
Benton Harbor, MI 49022