



SENTROL

12345 SW Leveton Dr.
Tualatin, OR 97062
Tel. 503.692.4052
Fax: 503.691.7566
800.547.2556
<http://www.sentrol.com>

August 7, 1998

Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

Gentlemen:

This equipment (BHS-FOB/RCVR) has been tested in accordance with the requirements contained in the appropriate Commission regulations. To the best of my knowledge, these tests were performed using measurement procedures consistent with industry of Commission standards and demonstrate that the equipment complies with the appropriate standards. Each unit manufactured, imported or marketed, as defined in the Commission's regulations, will conform to the sample(s) tested within the variations that can be expected due to quantity production and testing on a statistical basis. I further certify that the necessary measurements were made by CKC Laboratories, Inc., 5473A Clouds Rest, Mariposa, California 98338.

Sincerely,

Doug Marman
Vice President of Advanced Development
Sentrol

S E N T R O L
A R T I F E C H
M O O S E
I S T