



FCC ID: A94423376 IC: 3232A-423376

Bose Model 423376 Internal photos

Note: The product is molded of clear plastic and the FCC and Industry Canada labeling is clearly visible on the printed circuit board of the Left earcup.



Left Earcup assembled

Bose Corporation, 1 New York Ave, Framingham, MA 01701, USA Tel: (508) 766-6000 Fax: (508) 766-1145 Without written permission of laboratory, this report shall not be reproduced except in full. Report Number: EMC.423376.18.68.1 Form FL300959 Rev 04 BOSE CONFIDENTIAL



FCC ID: A94423376 IC: 3232A-423376




Right Earcup assembled

Form FL300959 Rev 04 BOSE CONFIDENTIAL



FCC ID: A94423376 IC: 3232A-423376




Right Earcup circuit board showing antenna location under solder mask.

Form FL300959 Rev 04 BOSE CONFIDENTIAL



FCC ID: A94423376 IC: 3232A-423376




Bottom side of Right Earcup

Form FL300959 Rev 04 BOSE CONFIDENTIAL

BUSE



FCC ID: A94423376 IC: 3232A-423376




Top side of Left Earcup circuit board showing product labeling

BUSE



FCC ID: A94423376 IC: 3232A-423376



Bottom side of Left Earcup circuit board

BUSE