

Report No.: 0602987
Receiving mode
(169.505MHz)
AC Mains


Tested By:Hong, Report No.:0602987

Scan Settings (1 Range)

Frequencies				Receiver Settings				
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF	60dB

Final Measurement: x QP / + AV
Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB

Transducer No.	Start	Stop	Name
1 15 9k 30M	EW0090		
21 9k 30M	EW0698		





Report No.: 0602987
Receiving mode
(169.505MHz)
AC Mains

Tested By:Hong, Report No.:0602987
Scan Settings (1 Range)
|----- Frequencies -----||----- Receiver Settings -----|
Start Stop Step IF BW Detector M-Time Atten Preamp OpRge
150k 30M 5k 10k PK+AV 10ms AUTO LN OFF 60dB
Final Measurement Results:

no Results

Report No.: 0602987
Receiving mode
(171.905MHz)
AC Mains


Tested By:Hong, Report No.:0602987

Scan Settings (1 Range)

Frequencies				Receiver Settings				
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF	60dB

Final Measurement: x QP / + AV
Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB

Transducer No.	Start	Stop	Name
1 15 9k 30M	EW0090		
21 9k 30M	EW0698		





Report No.: 0602987
Receiving mode
(171.905MHz)
AC Mains

Tested By: Hong, Report No.: 0602987

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results

Ctrl No.: NA