




REVISION RECORD			
LTR	ECO NO:	APPROVED:	DATE:







The case of the FIL1 must be soldered to ground for improvement the 1st Image Rejection




COMPANY:		TES		
TITLE:				
33-1197 RECEIVER				
DRAWN:	WENJIN	DATED:	25/Sep/07	REV:
CHECKED:	BUNNY	DATED:	25/Sep/07	C
QUALITY CONTROL:		DATED:		
RELEASED:		DATED:		
SCALE:		SHEET: 3 OF 3		

REVISION RECORD			
LTR	ECO NO:	APPROVED:	DATE:



COMPANY:				TES			
TITLE:				33-1197 RECEIVER			
DRAWN:	WENJIN	DATED:	25/Sep/07	CODE:	SIZE:	DRAWING NO:	REV:
CHECKED:	BUNNY	DATED:	25/Sep/07	A4			C
QUALITY CONTROL:		DATED:					
RELEASED:		DATED:					
SCALE:						SHEET: 1 OF 3	

REVISION RECORD			
LTR	ECO NO:	APPROVED:	DATE:



FCC ID: AAO3301197R

COMPANY:		TES		
TITLE:		33-1197 RECEIVER		
DRAWN:	WENJIN	DATED:	25/sep/07	
CHECKED:	BUNNY	DATED:	25/sep/07	
QUALITY CONTROL:		DATED:		
RELEASED:		DATED:		
SCALE:				SHEET: 2 OF 3