



Intertek Testing Services

ETL SEMKO

Mode = Tx

Report No.: 9912828

Tested By: Hong, Report No.: 9912828


Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement: x QP

Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB

Transducer No.	Start	Stop	Name
3	9k	30M	EI078



PAGE 1

Ctrl No.: N/A

Mode = Tx



Intertek Testing Services

ETL SEMKO

Report No.: 9912828

Tested By: Hong, Report No.: 9912828

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN	OFF 60dB

Final Measurement Results:

no Results

Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 9912828

Mode = Charging


Tested By: Hong, Report No.: 9912828

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN	OFF 60dB

Final Measurement: x QP
Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB

Transducer No.	Start	Stop	Name
3	9k	30M	EI078



Ctrl No.: N/A



Intertek Testing Services
ETL SEMKO

Mode = Charging

Report No.: 9912828

Tested By: Hong, Report No.: 9912828

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results

Ctrl No.: *N/A*



Intertek Testing Services

ETL SEMKO

Mode = Stand by

Report No.: 9912828

Tested By: Hong, Report No.: 9912828


Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement: x QP

Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB

Transducer No.	Start	Stop	Name
3	9k	30M	EI078



PAGE 1

Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Mode = Stand by

Report No.: 9912828

Tested By: Hong, Report No.: 9912828

Scan Settings (1 Range)

|----- Frequencies -----| |----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
-------	------	------	-------	----------	--------	-------	--------	-------

450k	30M	5k	10k	PK	20ms	AUTO	LN	OFF 60dB
------	-----	----	-----	----	------	------	----	----------

Final Measurement Results:

no Results

Ctrl No.: N/A