



# Intertek Testing Services

## ETL SEMKO

Report No.: 0103782

Mode: Talk

Tested By: Hong, Report No.: 0103782

Scan Settings (1 Range)

| Frequencies |      |      | Receiver Settings |          |        |       |        |          |
|-------------|------|------|-------------------|----------|--------|-------|--------|----------|
| Start       | Stop | Step | IF BW             | Detector | M-Time | Atten | Preamp | OpRge    |
| 450k        | 30M  | 5k   | 10k               | PK       | 20ms   | AUTO  | LN     | OFF 60dB |

Final Measurement: x QP


Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No. Start Stop Name

21 9k 30M EW0698



PAGE 1

Ctrl No.: N/A



# Intertek Testing Services

## ETL SEMKO

Report No.: 0103782  
Mode: Talk

Tested By: Hong, Report No.: 0103782

Scan Settings (1 Range)

[----- Frequencies -----] [----- Receiver Settings -----]

| Start | Stop | Step | IF BW | Detector | M-Time | Atten | Preamp | OpRge |
|-------|------|------|-------|----------|--------|-------|--------|-------|
| 450k  | 30M  | 5k   | 10k   | PK       | 20ms   | AUTO  | LN OFF | 60dB  |

Final Measurement

| Frequency | QP Level | QP Limit |
|-----------|----------|----------|
| MHz       | dBuV     | dBuV     |

|          |      |      |
|----------|------|------|
| 27.92500 | 27.0 | 48.0 |
|----------|------|------|

\* limit exceeded