



Intertek Testing Services

ETL SEMKO

Report No.: 0202556


Tested By: Ben, Report No.: 0202556

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement: x QP
Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB

Transducer No.	Start	Stop	Name
21	9k	30M	EW0698



Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 0202556

Tested By: Ben, Report No.: 0202556

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN	OFF 60dB

Final Measurement
Results:

Frequency	QP Level	QP Limit
MHz	dBuV	dBuV
0.45000	26.4	48.0
0.72000	26.3	48.0
0.76500	25.9	48.0
1.16500	21.2	48.0
1.31500	19.5	48.0

* limit
exceeded

Ctrl No.: N/A