



# Intertek Testing Services

## ETL SEMKO

Report No.: 0109396  
Mode: Talk

Tested By: Hong, Report No.: 0109396


Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement: x QP

Meas Time: 1 s  
Subranges: 16  
Acc Margin: 20dB

Transducer No. Start Stop Name  
21 9k 30M EW0698





# Intertek Testing Services

ETL SEMKO

Report No.: 0109396  
Mode: Talk

Tested By: Hong, Report No.: 0109396

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN	OFF 60dB

Final Measurement

no Results

Ctrl No.: N/A