



Class II Permissive Change Certification Application - Additional Information

May 30, 2003

American Telecommunications Certification Body, Inc.
6731 Whittier Avenue
Suite C110
McLean, VA 22101

RE : Class II Permissive Change Certification Application
FCC Tx ID : AB6NT800MFRM

Dear Sir/Madam

This letter is to respond the additional information that requested by ATCB. The answers to your requests are listed below:

Concern# 1) Please provide a separate exhibit containing the test configuration photographs from the Radiated testing (pages 24, 25, and 34).

Response: As suggested, the radiated emission setup pictures were included in the updated "Exhibit 7 - test setup photos.pdf" document and the document has been submitted to the ATCB web site under "Additional Information".

Concern# 2) Information in the test report summary introduction (Section 1.0) mentions Part 24. Please explain.

Response: The test report summary submitted was based on a test report template and the reference to Part 24 was removed. The updated "Exhibit 2 - Test report summary (NB DPM).pdf" has been submitted to the ATCB web site under "Additional Information".

Concern# 3) Section 4.1.4 mentions the maximum rated output power (above the tables) is 47.8 dBm. The results show 47.3 dBm. Please explain.

Response: The typo has been corrected and it should be 47.3 dBm. The updated "Exhibit 2A - Test report provided by Nortel.pdf" has been submitted to the ATCB web site under "Additional Information".

Concern# 4) The data given in Table 7 does not appear to match the plot provided. Please explain.

Response: The mistake has been corrected and the updated "Exhibit 2A - Test report provided by Nortel.pdf" has been submitted to the ATCB web site under "Additional Information".

Concern#5) The last reading in Table 10 appears incorrect. Please explain.

Response: The typo has been corrected and the updated "Exhibit 2 - Test report provided by Nortel.pdf" has been submitted to the ATCB web site under "Additional Information".



Please contact me for further information if necessary.

Sincerely,


Signature

Thomas Wong,
Regulatory Prime
Wireless Division, Nortel Networks
Tel: 403-769-2425 Fax: 403-769-7806
Email: thomaswg@nortelnetworks.com