

**From:** Thomas Wong [mailto:thomaswg@nortelnetworks.com]  
**Sent:** Thursday, March 25, 2004 3:46 PM  
**To:** dward ATCB  
**Subject:** RE: AB6NT800RM-CBTS\_ATCB001224

Dennis,

There is no tune-up in the field. All tune-up are done in the factory. In pg 9 of my "Exhibit 2 - 800MHz RM test report summary.pdf", we have put a statement down about the tune-up procedure. I am included here for you reference.

### 3.9 Tune-up Procedure

The tune-up tests will be performed as part of the factory testing on the 800MHz RM. This procedure includes power output levels, spurious emissions, and occupied bandwidth. There are no end-user adjustments that will have any effect on these settings. No tune-up testing is required in the field.

Please let me know whether it is sufficient. Thanks.

Regards,

*Thomas Wong  
CDMA/TDMA Regulatory Prime  
5050-40th St. N.E. Calgary, Alberta, T3J 4P8  
Tel: 403-769-2425 (ESN 758-2425)  
Fax:403-769-7806(ESN 758-7806)  
email: thomaswg@nortelnetworks.com*