

Photographs of the Device

Photographs – Index

<u>EXHIBIT</u>	<u>DESCRIPTION</u>
A1	ID Label Location
A2	FCC / IC Identification Label

APPLICANT: MOTOROLA SOLUTIONS

EQUIPMENT TYPE: ABZ99FT5101B
109AB-99FT5101B

Photographs of the Device

ID Label Location





APPLICANT: MOTOROLA SOLUTIONS

EQUIPMENT TYPE: ABZ99FT3095B
109AB-99FT3095B



Photographs of the Device

FCC / IC Identification Label



SN: 


 **MOTOROLA** SLR 8000

This device complies with Part 15 of the FCC rules, operation is subject to the condition that this device does not cause harmful interference

  **LISTED**
I.T.E.
E300595

Serial No: 433IYY0565
Model No: T8319A
S/Tanapa: PMUD3360A
FCC ID: ABZ99FT5101B
IC: 109AB-99FT5101B
HVIN: SLR 8000 - 800900B
US: ABZNINANPMLN6730
IC: 109AB-PMLN6730

MAC 1:  685E1CA4A5A8
MAC 2:  685E1CA4A5A9

 **BC**

100-240V ~ Max 10A 50/60 Hz
11.0-15.5V == 27A Max OR 32.0V == 23A Max

Mfr. Date:02/07/2023
Made in Mexico