



**Murata
Manufacturing Co., Ltd.**

Head Office
10-1 Higashikotari 1-chome,
Nagaokakyo-shi, Kyoto 617-8555 Japan

Date: December 8, 2009

DECLARATION

We, **Murata Manufacturing Co, Ltd.**, of the above address, hereby declare that because of the client software and the related drivers this device (FCC ID: ACJ-DY-WL10, IC: 216A- DYWL10) is not capable and cannot be made capable of transmitting a beacon signal in the DFS bands at the non-associated mode.

This device is a client only device and it cannot operate in ad-hoc or master configuration.

A handwritten signature in black ink, appearing to read "M. Hoshii", is written over a horizontal line. The signature is fluid and cursive.

Mitsuhiro Hoshii

Manager

Murata Manufacturing Co., Ltd.