



**APPENDIX 3: Photographs of test setup**

**Radiated Spurious Emission**



**Photo 1**



**Photo 2**

---

**UL Japan, Inc.**

**Ise EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999


Facsimile : +81 596 24 8124

**Worst Case Position**


**Module (Horizontal: X-axis / Vertical: X-axis)**

**Antenna (Horizontal: Y-axis / Vertical: X-axis)**


**Module X-axis**



**Antenna X-axis**




**Module Y-axis**



**Antenna Y-axis**



**Module Z-axis**



**Antenna Z-axis**



**End of Report**

**UL Japan, Inc.**

**Ise EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124