







1 SCHEMATIC DIAGRAM

1.1. APH & RPH



WIRING DIAGRAM

NOTE: * When replacing, check the lead wire colour as shown.
 * Colours shown by () indicate colours of lead wire connector housing.



SYMBOL	COLOR
OR	ORANGE
BL	BLUE
BR	BROWN
W	WHITE
Y	YELLOW
R	RED
GR	GRAY
B	BLACK

S-6N0

6 DIGITAL PROGRAMMER CIRCUIT

6.1. SCHEMATIC DIAGRAM

