

Date: 2019/11/14

Subject: Supersede request for FCC ID: ACQ-MG3

To Whom It May Concern:

We regret to inform you that revised test report needs to be uploaded to FCC website and remove original test report. The reason is HDD information is wrong..

11 Matches found for FCC ID ACQ-MG3

View Attachment	Exhibit Type	Date Submitted to FCC	Display Type	Date Available
POA	Cover Letter(s)	09/05/2019	pdf	09/06/2019
confidentiality	Cover Letter(s)	09/05/2019	pdf	09/06/2019
Ad hoc declaration	Cover Letter(s)	09/05/2019	pdf	09/06/2019
Product Equality declaration Letter	Cover Letter(s)	09/05/2019	pdf	09/06/2019
ID Label/Location Info	ID Label/Location Info	09/05/2019	pdf	09/06/2019
MPE	RF Exposure Info	09/05/2019	pdf	09/06/2019
Test Report co-location	Test Report	09/05/2019	pdf	09/06/2019
Test Report WLAN	Test Report	09/05/2019	pdf	09/06/2019
Test Report BLE	Test Report	09/05/2019	pdf	09/06/2019
Test Report Spot Check Revised	Test Report	09/06/2019	pdf	09/06/2019
Test Report 2425-2475 MHz Revise	Test Report	09/06/2019	pdf	09/06/2019

The error is required to correct so we submit this request for solving this issue.

Best regards

toy Cly

Gary Chang , Manager Report & Certification department <u>Tel:+886-3-271-8628</u> Email:Garychang@icertifi.com.tw