



**Bureau Veritas Consumer Products Services (H.K.) Ltd., Taoyuan Branch**

**香港商立德國際商品試驗有限公司桃園分公司**

No.19,Hwa Ya 2<sup>nd</sup> Rd,Kwei Shan Hsiang ,taoyuan Hsien ,Taiwan, R.O.C.

桃園縣龜山鄉華亞二路19號

**A D T** <http://www.adt.com.tw/> E-mail: service@adt.com.tw TEL: 886-3-3183232

FAX: 886-3-3270892

**FCC ID: ACQ-VAP2404**

**Date: 2012/6/25**

## **Description of Permissive Change**

This report is prepared for FCC class II permissive change.

This report is issued as a supplementary report to the original BVADT report no. RF111123C10. The differences compared with original report are using second source components & re-layout the PCB without change the RF emission characteristic and DFS operational software Therefore, only worst case channel was verified in the test report as approved by FCC in KDB 375986.

Gary Chang

Technical Manager

Bureau Veritas Consumer Products Services (H.K.) Ltd., Taoyuan Branch

Tel: 886-3-3183232 ext. 1608

Fax: 886-3-3270892

Email: Gary.chang@tw.bureauveritas.com