

## American Telecommunications Certification Body Inc.

6731 Whittier Ave, McLean, VA 22101

November 26, 2003

RE: Motorola (???)

FCC ID: ACQWA840G

I have a few comments on the above referenced Application.

- The application, label, and FRN number appear to match Motorola, however, Grantee code "ACQ" is listed under General Instrument Corp. Please explain. It appears the incorrect Grantee code may be given. Attached is a list of valid Motorola Grantee codes on the following page.
- 2) The device appears to contain 2 different types of antennas and also appears to be able to transmit out either antenna. Therefore radiated measurements should be provided for both antennas.
- 3) The test report states the antenna is 2 dBi (page 6) and 2.5 dBi (page 59), while the RF exposure exhibit states 2.5 dBi. Please correct exhibits to be consistent.
- 4) If the device may transmit out of either antenna, please provide information regarding the gain of both antennas.
- 5) One of the bandwidth plot appears to be missing from the report for CCK modulation. Please correct.
- 6) A schematic for the TX portion of the device is required as specified 2.1033(b)(5) for the RF section. However, if the TX portion of this device is an OEM part, as an alternative, you may provide a parts list that lists that shows that this part is provided by another manufacturer. Please provide either a schematic for the TX or parts list as specified.

Timothy R. Johnson Examining Engineer

mailto: tjohnson@AmericanTCB.com

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.

Page 2
November 26, 2003

