

Date of issue: 10 June 2011

Photographs of Furuno Radar Sensor DRS4A with Transceiver RTR-092A

1 Internal View


1.1 Inside View (with Top cover opened, showing Scanner Motor (upper) and Transceiver RTR-092A (lower))





Date of issue: 10 June 2011

1.2 Transceiver Top View





Date of issue: 10 June 2011


1.3 Transceiver Right Side View





Date of issue: 10 June 2011


1.4 Transceiver Top View (with Shield-cover removed, showing MD Board 03P9450 (upper) and PWR Board 03P9452 (lower))





Date of issue: 10 June 2011

1.5 Transceiver Right Side View (with Shield-cover removed, showing Magnetron E3571)






Date of issue: 10 June 2011

1.6 Transceiver Rear side View

Circulator



Magnetron (Inside)



Date of issue: 10 June 2011


1.7 Transceiver Bottom View





Date of issue: 10 June 2011


1.8 Transceiver Bottom View (with Shield-cover removed)





Date of issue: 10 June 2011

1.9 Transceiver Bottom View (with shield-covers removed, showing SPU Board 03P9455 (upper) and NMEA2000 Board 03P9462 (lower))



RXM Module