


Date of issue: 14 May 2015

Photographs of the Transceiver RTR-100 for Furuno Radar FAR-1518

1 PCBs


1.1 RFTB Board 03P9488 front side (attached on Antenna Unit RSB-120)





Date of issue: 14 May 2015


1.2 RFTB Board 03P9488 rear side (attached on Antenna Unit RSB-120)





Date of issue: 14 May 2015


1.3 HDBP Board 03P9347 front side





Date of issue: 14 May 2015

1.4 HDBP Board 03P9347 rear side





Furuno Labotech International Report no.: **FLI 01-15-006** Date of issue: 14 May 2015


1.5 PM32 Board 03P9559 front side





Furuno Labotech International Report no.: **FLI 01-15-006** Date of issue: 14 May 2015

1.6 PM32 Board 03P9559 rear side





Date of issue: 14 May 2015


1.7 RFC Board 03P9506 front side





Date of issue: 14 May 2015


1.8 RFC Board 03P9506 rear side





Date of issue: 14 May 2015


1.9 IF Board 03P9487 front side





Date of issue: 14 May 2015

1.10 IF Board 03P9487 rear side





Furuno Labotech International Report no.: **FLI 01-15-006** Date of issue: 14 May 2015


1.11 MIC Board 03P9505 front side





Date of issue: 14 May 2015


1.12 MIC Board 03P9505 rear side





Date of issue: 14 May 2015

1.13 MD Board 03P9489 front side





Date of issue: 14 May 2015

1.14 MD Board 03P9489 rear side

