


Date of issue: 30 September 2015

Photographs of Furuno Radar Sensor DRS6A X-Class


- 1 PCBs
- 1.1 MD Board 03P9597 Front side





Date of issue: 30 September 2015


1.2 MD Board 03P9597 Rear side





Date of issue: 30 September 2015

1.3 SPU Board 03P9598 Front side





Date of issue: 30 September 2015


1.4 SPU Board 03P9598 Rear side





Date of issue: 30 September 2015


1.5 MMIC Board 03P9604 Front side





Date of issue: 30 September 2015


1.6 MMIC Board 03P9604 Rear side





Date of issue: 30 September 2015


1.7 PWR Board 03P9607 Front side





Date of issue: 30 September 2015


1.8 PWR Board 03P9607 Rear side





Date of issue: 30 September 2015

1.9 MTR-DRV Board 15DJ002 Front side





Date of issue: 30 September 2015

1.10 MTR-DRV Board 15DJ002 Rear side

