


Labotech International Report no.: **LIC 01-16-033** Date of issue: 31 August 2016

Photographs of Furuno Radar Sensor DRS25A X-Class

1 PCBs


1.1 MD Board 03P9625 Front side





Date of issue: 31 August 2016


1.2 MD Board 03P9625 Rear side





Date of issue: 31 August 2016


1.3 SPU Board 03P9598 Front side





Date of issue: 31 August 2016

1.4 SPU Board 03P9598 Rear side





Date of issue: 31 August 2016


1.5 MMIC Board 03P9604 Front side





Labotech International Report no.: **LIC 01-16-033** Date of issue: 31 August 2016


1.6 MMIC Board 03P9604 Rear side





Date of issue: 31 August 2016


1.7 PWR Board 03P9607 Front side





Date of issue: 31 August 2016


1.8 PWR Board 03P9607 Rear side





Date of issue: 31 August 2016

1.9 MTR-DRV Board 14DJ003 Front side





Date of issue: 31 August 2016

1.10 MTR-DRV Board 14DJ003 Rear side

