




# **Photographs of Antenna Unit RSB-120**

#### 1 Internal view

1.1 Rear side view (with the scanner cover removed, showing HDBP Board 03P9347 and RFTB Board 03P9488)







1.2 Front side view (with the scanner cover removed, showing Transceiver module RTR-124)







1.3 Front side view (with Transceiver module removed, showing the scanner motor)





1.4 Front side view








1.5 Front side view (with the shield cover removed, showing IF Board 03P9487)







Date of issue: 19 September 2018



1.6 Front side view (with IF Board removed, showing MIC Board 03P9505 inside)











L/1BOTCH





Labotech International Co., Ltd. Document number: LIC 01-18-042 Date of issue: 19 September 2018


#### 1.8 Left side view








1.9 Left side view (with the shieldi cover removed, showing RFC Board 03P9506)








1.10 Left side view (with the shield cover removed, showing MD Board 03P9489)





Labotech International Co., Ltd. Document number: LIC 01-18-042 Date of issue: 19 September 2018


### 1.11 Rear side view





Labotech International Co., Ltd. Document number: LIC 01-18-042 Date of issue: 19 September 2018

## 1.12 Right side view







#### 1.13 Bottom side view






Labotech International Co., Ltd.

Document number: LIC 01-18-042

Date of issue: 19 September 2018

### 1.14 Bottom side view (with the shield cover removed, showing Pulse Transformer and Magnetron)



End of text