


Date of issue: 26 February 2021

Photographs of ANTENNA UNIT RSB-144-129 for MARINE RADAR FAR-2268DS

1 PCB


1.1 BUF board 03P9446, Front side





Labotech International Report No.: LIC 01-20-054 Date of issue: 26 February 2021


1.2 BUF board 03P9446, Rear side





Date of issue: 26 February 2021


1.3 RELAY board 03P9693, Front side





Labotech International Report No.: **LIC 01-20-054** Date of issue: 26 February 2021


1.4 RELAY board 03P9693, Rear side





Date of issue: 26 February 2021


1.5 PFN1 board 03P9431, Front side





Date of issue: 26 February 2021


1.6 PFN1 board 03P9431, Rear side





Labotech International Report No.: **LIC 01-20-054** Date of issue: 26 February 2021


1.7 PFN2 board 03P9445, Front side





Date of issue: 26 February 2021


1.8 PFN2 board 03P9445, Rear side





Date of issue: 26 February 2021


1.9 PFN3 board 03P9433, Front side





Date of issue: 26 February 2021


1.10 PFN3 board 03P9433, Rear side





Date of issue: 26 February 2021


1.11 SCR1 / SCR2 / SCR3 board 03P9549, Front side 1





Date of issue: 26 February 2021

1.12 SCR1 / SCR2 / SCR3 board 03P9549, Front side 2





Date of issue: 26 February 2021


1.13 IF board 03P9666, Front side





Date of issue: 26 February 2021


1.14 IF board 03P9666, Rear side





Date of issue: 26 February 2021


1.15 IF-TB board 03P9711, Front side





Date of issue: 26 February 2021


1.16 IF-TB board 03P9711, Rear side





Labotech International Report No.: LIC 01-20-054 Date of issue: 26 February 2021


1.17 MIC board 03P9569, Front side





Date of issue: 26 February 2021


1.18 MIC board 03P9569, Rear side





Date of issue: 26 February 2021


1.19 RFC board 03P9540, Front side





Date of issue: 26 February 2021


1.20 RFC board 03P9540, Rear side





Date of issue: 26 February 2021


1.21 MTR-DRV board 03P9560, Front side





Date of issue: 26 February 2021


1.22 MTR-DRV board 03P9560, Rear side





Date of issue: 26 February 2021


1.23 RF-TB board 03P9712, Front side





Date of issue: 26 February 2021


1.24 RF-TB board 03P9712, Rear side





Date of issue: 26 February 2021


1.25 BP-GEN board 03P9347, Front side





Date of issue: 26 February 2021

1.26 BP-GEN board 03P9347, Rear side



End of text