

Helen Zhao

Subject: FW: FW: Sanyo Electronic Co., Ltd., FCC ID: AEZNVN-4070, Assessment NO.: AN07T6870, Notice#1

Dear Helen,

Please see my reply, thank you.

Best Regards,
Gina

-----Original Message-----

Sent: Wednesday, June 06, 2007 12:14 PM

Subject: Sanyo Electronic Co., Ltd., FCC ID: AEZNVN-4070, Assessment

NO.: AN07T6870, Notice#1

Question #1: Based on system block diagram, the device is equipped with a 400MHz CPU. According to FCC15.33, radiated emission measurement shall be investigated from 30MHz to 2GHz. But the test report shows the radiated emission test was done upto 1GHz. Please provide additional test data for 1-2GHz.

Ans: Please see the page 16 of the revised test report.

Question #2: ANSI C63.4 section 11.1.1.2 Host not acting as the EUT specifies, "Instead at a minimum, its parallel and serial I/O ports shall have cabling connected to accessory equipments typically attached to these cables when a parallel and serial I/O port protocol port is available. Where they are available, a parallel and a serial I/O port protocol port shall be connected." But the test report and test setup photos do not show that above requirement has met. Please provide the updated test report and test setup photos.

Ans: Please see the page 5 of the revised test report and test set up photos.

Best Regards,
Helen Zhao

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

6/6/2007