



Icom Inc.
1-1-32, Kamiminami, Hirano-ku, Osaka 547-0003 Japan.
Phone : 06 6793 5302 Fax : 06 6793 0013
e-mail: world_support@icom.co.jp

FCC Labeling Requirements and Information

March 10, 2006

American Telecommunications Certification Body, Inc.
6731 Whittier Avenue
Suite C110
McLean, VA 22101

RE: FCC Labeling Requirements
FCC ID: AFJ287900

The following label information is required by the FCC Rules and Regulations for certified devices.
Also attached, please find marketing information required by the FCC Rules and Regulations.

Thank you for your attention to these matters.

Icom Incorporated


Yoshiteru Yano
General Manager

ICOM

IC-R2500

FCC ID:AFJ287900

Icom Inc.

MADE IN JAPAN

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

WARNING:MODIFICATION OF THIS DEVICE TO RECEIVE CELLULAR RADIOTELEPHONE SERVICE SIGNALS IS PROHIBITED UNDER FCC RULES AND FEDERAL LAW.

SERIAL NO.

0000000



ICOM

IC-PCR2500

FCC ID:AFJ287900

Icom Inc.

MADE IN JAPAN

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

WARNING: MODIFICATION OF THIS DEVICE TO RECEIVE CELLULAR RADIOTELEPHONE SERVICE SIGNALS IS PROHIBITED UNDER FCC RULES AND FEDERAL LAW.

SERIAL NO.

0000000





ICOM IC-F287900
Accessories: **FCC ID: AFJ287900**
Model: AFJ287900

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

WARNING: OPERATION OF THIS DEVICE TO RECEIVE CELLULAR RADIO/TELEPHONE SERVICE SIGNALS IS PROHIBITED UNDER FCC RULES AND FEDERAL LAW.

Model: 0180084