



Icom Inc.

6-9-16, Kamihigashi, Hirano-ku, Osaka, 547, Japan.  
Phone : 06 6793 5302 Fax : 06 6793 0013  
E-Mail : Export@icom.co.jp

MAILING ADDRESS:

1-6-19 Kamikurazukuri,  
Hirano-ku, Osaka 547-0004  
Japan

January.07.2000

Federal Communications Commission  
Authorization & Evaluation Division  
7435 Oakland Mills Road  
Colombia, Maryland 21046

Gentlemen:

This letter will authorize the appointment of M ORTON FLOM,  
P. Eng., and/or M. Flom Associates, Inc. to act as our Agent in all FCC matters.

This appointment is effective until otherwise notified by us.

This is to advise that we are in full compliance with the Anti-Drug Abuse Act.  
The Applicant is not subject to a denial of federal benefits pursuant to Section 5301 of the Anti-Drug Abuse Act of 1988, 12 USC 862, and no party to the application is subject to a denial of federal benefits pursuant to that section.

Sincerely,

Icom Incorporated.

A handwritten signature in black ink, appearing to read 'Tadashi Maebayashi', written over the printed name.

Tadashi Maebayashi  
Export division director.



icom Inc.  
6-9-16, Kamihigashi, Hirano-ku, Osaka, 547, Ja  
Phone : +81 6 793 5302 Fax : +81 6 793 00  
E-mail : export@icom.co.jp

Sept .18.1999

ICOM INCORPORATED  
1-6-19 Kamikurazukur  
Hirano-Ku  
Osaka, Japan 547

Federal Communications Commission  
Authorization & Evaluation Division  
7435 Oakland Mills Road  
Colombia, Maryland 21046

Gentlemen:

Reference: AFJ-IC-F4TR-2

This equipment meets the requirements of the FCC Rules ,  
Parts 90.203(e) and (g) , as applicable.

Programming of this product's transmit frequencies can be performed  
ONLY by the manufacturer or by service or by maintenance personnel.  
The operator cannot program transmit frequencies using the  
equipment's external operation controls.

Sincerely,

icom Incorporated.

Tadashi Maebayashi  
Export division director.



Icom America, Inc.  
Corporate Headquarters  
2-80 1160 Ave. N.E.  
Bldg. 1000  
Folsom, CA 95630  
Phone: (415) 434-8155  
Fax: (415) 94-1509  
E-mail: [usinfo@icom.com](mailto:usinfo@icom.com) (415) 454-7819

March 16, 2000

To Whom It May Concern:

The United States Coast Guard and NOAA have reported to the FCC an occurrence of unauthorized transmissions in the 406-406.1 MHz band. This band is reserved for use by distress beacons.

The purpose of this Service Bulletin is to remind all Icom Authorized Dealers and Servicers not to program the 406-406.1 MHz frequency range into and Icom transceiver capable of transmitting in this frequency range.

Sincerely,

A handwritten signature in black ink, appearing to read 'Masaaki Takahashi', written in a cursive style.

Masaaki Takahashi  
New Product Manager