



Icom Inc.

1-1-32, Kamiminami, Hirano-ku, Osaka, 547-0003 Japan  
Phone : 06 6793 5302 Fax : 06 6793 0013  
E-Mail: [export@icom.co.jp](mailto:export@icom.co.jp)

April 3, 2002

Federal Communications Commission  
Authorization & Evaluation Division  
7435 Oakland Mills Road  
Colombia, Maryland 21046

RE: Blocked Frequency  
FCC ID: AFJ IC-F620-1

Dear Sir/ Madam

The frequencies 400-406.1MHz are blocked to the AFJ IC-F620-1 user by the radio cloning software. Because the radio does not have a continuous tuning mode (VFO), it can only be used on channel programmed with the cloning software. Only the manufacture and authorized dealers have this software. Therefore it is not possible for the user to operate in this frequency region.

Thank you for your attention to this matter.

Sincerely

Icom Incorporated

青木 奇  
Takashi Aoki

General Manager