

Icom America, Inc.

Corporate Headquarters 2380 116th Ave. N.E. Bellevue, Washington 98004 Phone: (425) 454-8155 Fax: (425) 454-1509 Customer Service: (425) 454-7619

December 3, 1999

Federal Communications Commission Authorization & Evaluation Division 7435 Oakland Mills Road Columbia, Maryland 21046

Attention:

Authorization & Evaluation Division

Applicant: ICOM INCORPORATED

Equipment: FCC ID: AFJIC-R75

FCC Rules: Part 2.1043

Subject:

Updated information for Class II Permissive Change

Dear Sir/Madam

In order to comply with new FCC scanner regulation, a permanently affixed warning label has been attached to the products as per FCC Part 15.121 (f)(1).

Otherwise, the device is internally and electronically same.

About test report requirement for at least 38dB image rejection of cellular service, the device operates below 520MHz, and is impossible to test and measure the cellular image rejection for Cellular Service

Therefore no cellular image test report can be provided

Takkle

Best regards

Masaaki Takahashi

Manager, New Product Development

MT:sg