


TYPE OF EXHIBIT: FCC PART 15 WARNING LABEL
FCC PART: 15.19 (a)(1)
MANUFACTURER: RITRON, INC.
505 West Carmel Drive
Carmel, IN 46032
FCC ID: AIERIT27-150
MODELS: LM-V150, LPA-V150
DATE: September 26, 2007

The following drawing specifies the FCC Part 15 Warning label for the LM-V150 and LPA-V150. Photographs are included to indicate the position of the label on each model's case.

Signed: 
Michael A. Pickard - Project Engineer

RITRON, INC. • 505 West Carmel Drive • Carmel, Indiana 46032
TEL: 317-846-1201 • FAX: 317-846-4978 • <http://www.ritron.com>

Ritron Item: 14230554
Description: LABEL, FCC PART 15 WARNING
Vendor Part Numbers: Identco# TTL308-700-10
Identco# TTRR-D3.54ZJ
Revision Date: September 26, 2007

Description:

The FCC Part 15 Warning label will be made in house by manufacturing. The ELP 310 thermal transfer printer will be used with glossy white poly label (RTN# 14290007). Identco# TTL308-700-10, a 1.5" by 0.75" label, is the approved material. The approved ribbon is Identco# TTRR-D3.54ZJ.

Drawing:

This device complies with part 15 of the FCC Rules. Operation is subject to the condition that this device does not cause harmful interference.

Chief Eng. _____

Project Eng. _____

Sales: _____

Manufacturing: _____



EXHIBIT: LM-V150 case bottom showing location of FCC Part 15 Warning label
 (Photo is for location only, actual label is per attached drawing)

FCC ID: AIERIT27-150



EXHIBIT: LPA-V150 case bottom showing location of FCC Part 15 Warning label
 (Photo is for location only, actual label is per attached drawing)

FCC ID: AIERIT27-150