



Ritron, Inc.
505 W. Carmel Drive • Carmel, IN 46032-7564
P.O. Box 1998 • Carmel, IN 46082-1998
Ph: 317-846-1201
Fax: 317-846-4978
Email: ritron@ritron.com
Web Site: www.ritron.com

January 30, 2012

Ritron Inc.
505 West Carmel Dr.
Carmel, IN 46032

Timco Engineering Inc.
849 NW State Road 45
Newberry, Florida 32669

REFERENCE: JOB 157UC12

Dear Sir/Madam:

Ritron, Inc. will offer the following Part 90 and Part 95J models with Part 15B receiver AIERIT32-433-RCVR installed. Should Ritron desire installation in other products, tests will be conducted to assure compliance per FCC Part 2.1043(b)(1) Class I permissive change. The Part 15B receiver AIERIT32-433-RCVR will not be offered for retrofit into products already deployed in the field.

<u>Model</u>	<u>TX FCC ID</u>
RQT-151-RCVR	AIERIT32-151
RQT-151M-RCVR	AIERIT32-151M
RQT-152-RCVR	AIERIT32-152
RQT-152M-RCVR	AIERIT32-152M
RQT-451-RCVR	AIERIT32-451
RQT-452-RCVR	AIERIT32-452

Sincerely,

Michael A. Pickard
Project Engineer
Ritron, Inc.